

Date: <03> <2015>  
Document type: Technical product paper

## **TETRA Terminal Device VS4000 – Tune Up Informations**

FCC ID: X5YVS4000-806-870  
Product Name: VS4000 806-870

### **Tune up Informations**

No tune up procedure is required by technician or user after the device has left the factory to match its specifications on the working frequency.

The VS4000 device has no manual trimmers or adjustments that can be manually done on it acting directly on the device itself



End document