


FCC Part 27


B4 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:39:35

1.4MHz_Low_QPSK_6@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:39:53

1.4MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:40:12

1.4MHz_Middle_QPSK_6@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:40:30

1.4MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:40:49

1.4MHz_High_QPSK_6@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:41:07

3MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:41:54

3MHz_Low_QPSK_15@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:42:12

3MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:42:31

3MHz_Middle_QPSK_15@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:42:50

3MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:43:09

3MHz_High_QPSK_15@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:43:28

5MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:44:16

5MHz_Low_QPSK_25@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:44:35

5MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:44:54

5MHz_Middle_QPSK_25@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:45:14

5MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:45:33

5MHz_High_QPSK_25@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:45:53

10MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:46:42

10MHz_Low_QPSK_50@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:47:02

10MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:47:21

10MHz_Middle_QPSK_50@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:47:40

10MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:48:00

10MHz_High_QPSK_50@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:48:19

15MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:49:06

15MHz_Low_QPSK_75@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:49:26

15MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:49:45

15MHz_Middle_QPSK_75@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:50:04

15MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:50:23

15MHz_High_QPSK_75@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:50:42

20MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:51:38

20MHz_Low_QPSK_100@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:51:58

20MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:52:17

20MHz_Middle_QPSK_100@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:52:36

20MHz_High_QPSK_1@0



ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:52:55


20MHz_High_QPSK_100@0



ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 19:53:14


B7, Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:05:55

5MHz_Low_QPSK_25@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:06:17

5MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:06:40

5MHz_Middle_QPSK_25@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:07:03

5MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:07:26

5MHz_High_QPSK_25@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:07:48

10MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:09:51

10MHz_Low_QPSK_50@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:10:15

10MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:10:38

10MHz_Middle_QPSK_50@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:11:02

10MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:11:25

10MHz_High_QPSK_50@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:11:49

15MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:13:50

15MHz_Low_QPSK_75@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:14:13

15MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:14:37

15MHz_Middle_QPSK_75@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:15:01

15MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:15:24

15MHz_High_QPSK_75@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:15:47

20MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:16:39

20MHz_Low_QPSK_100@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:17:02

20MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:17:25

20MHz_Middle_QPSK_100@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:17:48

20MHz_High_QPSK_1@0



ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:18:11


20MHz_High_QPSK_100@0



ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:18:34


B66 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:19:34

1.4MHz_Low_QPSK_6@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:19:54

1.4MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:20:15

1.4MHz_Middle_QPSK_6@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:20:35

1.4MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:20:55

1.4MHz_High_QPSK_6@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:21:16

3MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:22:02

3MHz_Low_QPSK_15@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:22:22

3MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:22:42

3MHz_Middle_QPSK_15@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:23:01

3MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:23:21

3MHz_High_QPSK_15@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:23:41

5MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:24:27

5MHz_Low_QPSK_25@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:24:47

5MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:25:07

5MHz_Middle_QPSK_25@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:25:27

5MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:25:47

5MHz_High_QPSK_25@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:26:08

10MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:26:57

10MHz_Low_QPSK_50@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:27:18

10MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:27:40

10MHz_Middle_QPSK_50@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:28:01

10MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:28:23

10MHz_High_QPSK_50@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:28:44

15MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:29:33

15MHz_Low_QPSK_75@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:29:53

15MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:30:15

15MHz_Middle_QPSK_75@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:30:36

15MHz_High_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:30:58

15MHz_High_QPSK_75@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:31:19

20MHz_Low_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:32:20

20MHz_Low_QPSK_100@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:32:42

20MHz_Middle_QPSK_1@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:33:03

20MHz_Middle_QPSK_100@0




ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:33:24

20MHz_High_QPSK_1@0



ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:33:46

20MHz_High_QPSK_100@0



ProjectNo.:2402U80198E-RF Tester:Loge Long
Date: 16.JUN.2024 20:34:07