



10MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 11:54:24

10MHz_Low_QPSK_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 11:53:51

10MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 11:55:29

10MHz_Low_16QAM_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 11:54:56

10MHz_High_QPSK_1@49




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 11:56:44

10MHz_High_QPSK_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 11:56:11

10MHz_High_16QAM_1@49




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20,JUL,2024 11:57:49

10MHz_High_16QAM_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20,JUL,2024 11:57:16

15MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20,JUL,2024 12:02:03

15MHz_Low_QPSK_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20,JUL,2024 12:01:22

15MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20,JUL,2024 12:03:25

15MHz_Low_16QAM_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20,JUL,2024 12:02:44

15MHz_High_QPSK_1@74




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:05:02

15MHz_High_QPSK_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:04:19

15MHz_High_16QAM_1@74




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:06:26

15MHz_High_16QAM_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:05:44

20MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:11:22

20MHz_Low_QPSK_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:10:29

20MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:13:08

20MHz_Low_16QAM_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:12:16

20MHz_High_QPSK_1@99




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:15:03

20MHz_High_QPSK_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:14:11

20MHz_High_16QAM_1@99



ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:16:47

20MHz_High_16QAM_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:15:55


FCC Part 27

B4 , Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0



1.4MHz_High_QPSK_1@5



1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 12:19:58

1.4MHz_High_16QAM_6@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 12:19:37

3MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 12:21:37

3MHz_Low_QPSK_15@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 12:21:13

3MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 12:22:25

3MHz_Low_16QAM_15@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 12:22:01

3MHz_High_QPSK_1@14




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 12:23:26

3MHz_High_QPSK_15@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 12:23:01

3MHz_High_16QAM_1@14




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 12:24:15

3MHz_High_16QAM_15@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 12:23:50

5MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 12:25:41

5MHz_Low_QPSK_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 12:25:19

5MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:26:17

5MHz_Low_16QAM_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:26:04

5MHz_High_QPSK_1@24




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:27:25

5MHz_High_QPSK_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:27:01

5MHz_High_16QAM_1@24




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:28:10

5MHz_High_16QAM_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:27:48

10MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 12:31:23

10MHz_Low_QPSK_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 12:30:50

10MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 12:32:29

10MHz_Low_16QAM_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 12:31:56

10MHz_High_QPSK_1@49




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 12:33:47

10MHz_High_QPSK_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 12:33:14

10MHz_High_16QAM_1@49




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 12:34:54

10MHz_High_16QAM_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 12:34:20

15MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 12:36:58

15MHz_Low_QPSK_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 12:36:16

15MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 12:38:21

15MHz_Low_16QAM_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 12:37:40


15MHz_High_QPSK_1@74




15MHz_High_QPSK_75@0




15MHz_High_16QAM_1@74




15MHz_High_16QAM_75@0




20MHz_Low_QPSK_1@0



20MHz_Low_QPSK_100@0




20MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:46:38

20MHz_Low_16QAM_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:45:45

20MHz_High_QPSK_1@99




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:48:35

20MHz_High_QPSK_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:47:42

20MHz_High_16QAM_1@99



ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:50:20


20MHz_High_16QAM_100@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 12:49:27


B7 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:26:13

5MHz_Low_QPSK_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:26:01

5MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:26:16

5MHz_Low_16QAM_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:26:25

5MHz_High_QPSK_1@24




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:27:17

5MHz_High_QPSK_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:27:05

5MHz_High_16QAM_1@24




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 13:27:41

5MHz_High_16QAM_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 13:27:28

10MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 13:28:55

10MHz_Low_QPSK_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 13:28:43

10MHz_Low_16QAM_1@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 13:29:20

10MHz_Low_16QAM_50@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 13:29:07