



10MHz_High_QPSK_1@49




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:30:01

10MHz_High_QPSK_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:29:49

10MHz_High_16QAM_1@49




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:30:25

10MHz_High_16QAM_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:30:13

15MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:31:39

15MHz_Low_QPSK_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:31:28

15MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:32:04

15MHz_Low_16QAM_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:31:52

15MHz_High_QPSK_1@74




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:32:45

15MHz_High_QPSK_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:32:32

15MHz_High_16QAM_1@74




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:33:08

15MHz_High_16QAM_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20.JUL.2024 13:32:56

20MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 13:35:58

20MHz_Low_QPSK_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 13:35:45

20MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 13:36:22

20MHz_Low_16QAM_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 13:36:10

20MHz_High_QPSK_1@99




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 13:37:20

20MHz_High_QPSK_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 20,JUL,2024 13:36:54

20MHz_High_16QAM_1@99



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 13:37:45


20MHz_High_16QAM_100@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 13:37:33


B38 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 10:47:09

5MHz_Low_QPSK_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 10:47:49

5MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 10:48:28

5MHz_Low_16QAM_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 10:49:29

5MHz_High_QPSK_1@24




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 10:50:34

5MHz_High_QPSK_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 10:51:13

5MHz_High_16QAM_1@24




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 10:51:53

5MHz_High_16QAM_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 10:52:32

10MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 10:54:45

10MHz_Low_QPSK_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 10:55:21

10MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 10:55:58

10MHz_Low_16QAM_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 10:56:35

10MHz_High_QPSK_1@49




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 10:57:45

10MHz_High_QPSK_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 10:58:29

10MHz_High_16QAM_1@49




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 10:59:13

10MHz_High_16QAM_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:00:40


15MHz_Low_QPSK_1@0




15MHz_Low_QPSK_75@0




15MHz_Low_16QAM_1@0




15MHz_Low_16QAM_75@0




15MHz_High_QPSK_1@74



15MHz_High_QPSK_75@0




15MHz_High_16QAM_1@74




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:07:22

15MHz_High_16QAM_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:08:07

20MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:10:04

20MHz_Low_QPSK_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:10:43

20MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:11:21

20MHz_Low_16QAM_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:11:59

20MHz_High_QPSK_1@99




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:13:29

20MHz_High_QPSK_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:14:17

20MHz_High_16QAM_1@99



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:15:05


20MHz_High_16QAM_100@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:15:53


B41 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:18:49

5MHz_Low_QPSK_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:19:41

5MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:20:32

5MHz_Low_16QAM_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:21:24

5MHz_High_QPSK_1@24




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:22:53

5MHz_High_QPSK_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:23:31

5MHz_High_16QAM_1@24




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:24:08

5MHz_High_16QAM_25@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:24:46


10MHz_Low_QPSK_1@0




10MHz_Low_QPSK_50@0




10MHz_Low_16QAM_1@0




10MHz_Low_16QAM_50@0




10MHz_High_QPSK_1@49



10MHz_High_QPSK_50@0




10MHz_High_16QAM_1@49




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:34:42

10MHz_High_16QAM_50@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 11:36:00

15MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 14:36:31

15MHz_Low_QPSK_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 14:37:10

15MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 14:37:48

15MHz_Low_16QAM_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 24.JUL.2024 14:38:27

15MHz_High_QPSK_1@74




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 14:39:35

15MHz_High_QPSK_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 14:40:12

15MHz_High_16QAM_1@74




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 14:40:12

15MHz_High_16QAM_75@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 14:48:11

20MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:44:10

20MHz_Low_QPSK_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:44:48

20MHz_Low_16QAM_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:45:27

20MHz_Low_16QAM_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:46:06

20MHz_High_QPSK_1@99




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:48:25

20MHz_High_QPSK_100@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:49:05

20MHz_High_16QAM_1@99



ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:49:45

20MHz_High_16QAM_100@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
 Date: 24.JUL.2024 11:50:25