



3MHz_High_QPSK_1@14




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:55:52

3MHz_High_QPSK_15@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:56:37

3MHz_High_16QAM_1@14




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:57:23

3MHz_High_16QAM_15@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:58:09

5MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:00:40

5MHz_Low_QPSK_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:01:24

5MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 22:02:08

5MHz_Low_16QAM_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 22:02:52

5MHz_High_QPSK_1@24




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 22:03:52

5MHz_High_QPSK_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 22:04:36

5MHz_High_16QAM_1@24




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 22:05:22

5MHz_High_16QAM_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 22:06:08

10MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:09:32

10MHz_Low_QPSK_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:10:26

10MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:11:20

10MHz_Low_16QAM_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:12:14

10MHz_High_QPSK_1@49




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:23:14

10MHz_High_QPSK_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:24:06

10MHz_High_16QAM_1@49



ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 22:24:59

10MHz_High_16QAM_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 22:25:52

FCC Part 24E


B2 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:53:02

1.4MHz_Low_QPSK_6@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:53:21

1.4MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:53:41

1.4MHz_Low_16QAM_6@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:53:59

1.4MHz_High_QPSK_1@5




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:54:36

1.4MHz_High_QPSK_6@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:55:08

1.4MHz_High_16QAM_1@5




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:55:28

1.4MHz_High_16QAM_6@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:55:47

3MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:57:50

3MHz_Low_QPSK_15@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:58:09

3MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:58:28

3MHz_Low_16QAM_15@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:58:47

3MHz_High_QPSK_1@14




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:59:20

3MHz_High_QPSK_15@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:59:40

3MHz_High_16QAM_1@14




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:00:00

3MHz_High_16QAM_15@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:00:20

5MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:02:14

5MHz_Low_QPSK_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:02:28

5MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:02:42

5MHz_Low_16QAM_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:02:56

5MHz_High_QPSK_1@24




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:03:24

5MHz_High_QPSK_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:03:38

5MHz_High_16QAM_1@24




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:03:51

5MHz_High_16QAM_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:04:05

10MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:06:10

10MHz_Low_QPSK_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:06:23

10MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:06:37

10MHz_Low_16QAM_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:06:51

10MHz_High_QPSK_1@49




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:07:18

10MHz_High_QPSK_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:07:31

10MHz_High_16QAM_1@49




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:07:45

10MHz_High_16QAM_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:07:59

15MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:10:09

15MHz_Low_QPSK_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:10:21

15MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:10:33

15MHz_Low_16QAM_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:10:46

15MHz_High_QPSK_1@74




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:11:10

15MHz_High_QPSK_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:11:22

15MHz_High_16QAM_1@74




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:11:34

15MHz_High_16QAM_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:11:46

20MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:14:09

20MHz_Low_QPSK_100@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:14:22

20MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:14:35

20MHz_Low_16QAM_100@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:14:48

20MHz_High_QPSK_1@99




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:15:14

20MHz_High_QPSK_100@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:15:27

20MHz_High_16QAM_1@99



ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:15:40

20MHz_High_16QAM_100@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:15:54

FCC Part 27


B4 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:16:57

1.4MHz_Low_QPSK_6@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:17:16

1.4MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:17:39

1.4MHz_Low_16QAM_6@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:18:01

1.4MHz_High_QPSK_1@5




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:18:37

1.4MHz_High_QPSK_6@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:18:58

1.4MHz_High_16QAM_1@5




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:19:19

1.4MHz_High_16QAM_6@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:19:40

3MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:21:46

3MHz_Low_QPSK_15@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:22:05

3MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:22:25

3MHz_Low_16QAM_15@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:22:44

3MHz_High_QPSK_1@14




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 21:23:17

3MHz_High_QPSK_15@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 21:23:37

3MHz_High_16QAM_1@14




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 21:23:56

3MHz_High_16QAM_15@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 21:24:16

5MHz_Low_QPSK_1@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 21:26:53

5MHz_Low_QPSK_25@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 21:27:06