



5MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:27:20

5MHz_Low_16QAM_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:27:34

5MHz_High_QPSK_1@24




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:28:02

5MHz_High_QPSK_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:28:16

5MHz_High_16QAM_1@24




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:28:30

5MHz_High_16QAM_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:28:44

10MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:31:21

10MHz_Low_QPSK_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:31:37

10MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:31:53

10MHz_Low_16QAM_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:32:09

10MHz_High_QPSK_1@49




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:32:42

10MHz_High_QPSK_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:32:58

10MHz_High_16QAM_1@49




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:33:14

10MHz_High_16QAM_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:33:30

15MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:35:44

15MHz_Low_QPSK_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:35:58

15MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:36:13

15MHz_Low_16QAM_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:36:27

15MHz_High_QPSK_1@74




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:36:56

15MHz_High_QPSK_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:37:10

15MHz_High_16QAM_1@74




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:37:23

15MHz_High_16QAM_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:37:37

20MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:39:49

20MHz_Low_QPSK_100@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 21:40:04

20MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:40:19

20MHz_Low_16QAM_100@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:40:34

20MHz_High_QPSK_1@99




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:41:00

20MHz_High_QPSK_100@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:41:14

20MHz_High_16QAM_1@99



ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:41:29


20MHz_High_16QAM_100@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 21:41:43


B7 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 22:26:36

5MHz_Low_QPSK_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 22:26:47

5MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 22:26:58

5MHz_Low_16QAM_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 22:27:10

5MHz_High_QPSK_1@24




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 22:27:36

5MHz_High_QPSK_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 22:27:47

5MHz_High_16QAM_1@24




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:27:58

5MHz_High_16QAM_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:28:09

10MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:30:09

10MHz_Low_QPSK_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:30:20

10MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:30:31

10MHz_Low_16QAM_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 22:30:42

10MHz_High_QPSK_1@49




ProjectNo.:2402W90636E-RF Teeter:Loge Long
 Date: 26.AUG.2024 22:31:08

10MHz_High_QPSK_50@0




ProjectNo.:2402W90636E-RF Teeter:Loge Long
 Date: 26.AUG.2024 22:31:20

10MHz_High_16QAM_1@49




ProjectNo.:2402W90636E-RF Teeter:Loge Long
 Date: 26.AUG.2024 22:31:30

10MHz_High_16QAM_50@0




ProjectNo.:2402W90636E-RF Teeter:Loge Long
 Date: 26.AUG.2024 22:31:41

15MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Teeter:Loge Long
 Date: 26.AUG.2024 22:33:52

15MHz_Low_QPSK_75@0




ProjectNo.:2402W90636E-RF Teeter:Loge Long
 Date: 26.AUG.2024 22:34:02

15MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 28.AUG.2024 22:34:13

15MHz_Low_16QAM_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 28.AUG.2024 22:34:23

15MHz_High_QPSK_1@74




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 28.AUG.2024 22:34:48

15MHz_High_QPSK_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 28.AUG.2024 22:34:59

15MHz_High_16QAM_1@74




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 28.AUG.2024 22:35:10

15MHz_High_16QAM_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 28.AUG.2024 22:35:21

20MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Teeter:Loge Long
 Date: 28.AUG.2024 22:37:28

20MHz_Low_QPSK_100@0




ProjectNo.:2402W90636E-RF Teeter:Loge Long
 Date: 28.AUG.2024 22:37:39

20MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Teeter:Loge Long
 Date: 28.AUG.2024 22:37:50

20MHz_Low_16QAM_100@0




ProjectNo.:2402W90636E-RF Teeter:Loge Long
 Date: 28.AUG.2024 22:38:02

20MHz_High_QPSK_1@99




ProjectNo.:2402W90636E-RF Teeter:Loge Long
 Date: 28.AUG.2024 22:38:26

20MHz_High_QPSK_100@0




ProjectNo.:2402W90636E-RF Teeter:Loge Long
 Date: 28.AUG.2024 22:38:37

20MHz_High_16QAM_1@99



ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 22:38:48


20MHz_High_16QAM_100@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 22:38:59


B38 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:22:37

5MHz_Low_QPSK_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:23:16

5MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:23:56

5MHz_Low_16QAM_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:24:36

5MHz_High_QPSK_1@24




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:25:51

5MHz_High_QPSK_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:26:30

5MHz_High_16QAM_1@24




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:27:09

5MHz_High_16QAM_25@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:27:48

10MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:30:09

10MHz_Low_QPSK_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:30:45

10MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:31:22

10MHz_Low_16QAM_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:31:58

10MHz_High_QPSK_1@49




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:33:08

10MHz_High_QPSK_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:33:50

10MHz_High_16QAM_1@49




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:34:33

10MHz_High_16QAM_50@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:35:16

15MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:37:40

15MHz_Low_QPSK_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:38:17

15MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:38:54

15MHz_Low_16QAM_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:39:31

15MHz_High_QPSK_1@74



ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:40:46

15MHz_High_QPSK_75@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:41:32