



15MHz_High_16QAM_1@74




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:42:18

15MHz_High_16QAM_75@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:43:03

20MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:45:46

20MHz_Low_QPSK_100@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:46:24

20MHz_Low_16QAM_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:47:03

20MHz_Low_16QAM_100@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:47:41

20MHz_High_QPSK_1@99




ProjectNo.:2402W90636E-RF Teeter:Loge Long
Date: 29.AUG.2024 13:49:03

20MHz_High_QPSK_100@0




ProjectNo.:2402W90636E-RF Teeter:Loge Long
Date: 29.AUG.2024 13:49:51

20MHz_High_16QAM_1@99



ProjectNo.:2402W90636E-RF Teeter:Loge Long
Date: 29.AUG.2024 13:50:40

20MHz_High_16QAM_100@0




ProjectNo.:2402W90636E-RF Teeter:Loge Long
Date: 29.AUG.2024 13:51:28

Spurious Emissions at Antenna Terminal


FCC Part 22H

B5 , Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Middle_QPSK_1@0




1.4MHz_High_QPSK_1@0




3MHz_Low_QPSK_1@0




3MHz_Middle_QPSK_1@0



3MHz_High_QPSK_1@0




5MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:20:35

5MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:21:10

5MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:21:44

10MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:24:12

10MHz_Middle_QPSK_1@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:24:46

10MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:25:20


FCC Part 24E

B2 , Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Middle_QPSK_1@0




1.4MHz_High_QPSK_1@0




3MHz_Low_QPSK_1@0




3MHz_Middle_QPSK_1@0



3MHz_High_QPSK_1@0




5MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 19:31:16

5MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 19:31:54

5MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 19:32:32

10MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 19:34:43

10MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 19:35:22

10MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 19:36:01

15MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 19:38:18

15MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 19:38:58

15MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 19:39:37

20MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 19:42:05

20MHz_Middle_QPSK_1@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 19:42:45

20MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 19:43:26


FCC Part 27

B4 , Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Middle_QPSK_1@0




1.4MHz_High_QPSK_1@0




3MHz_Low_QPSK_1@0




3MHz_Middle_QPSK_1@0



3MHz_High_QPSK_1@0




5MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 19:57:18

5MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 19:58:01

5MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 19:58:44

10MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:01:34

10MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:02:14

10MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:02:54

15MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:05:32

15MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:06:09

15MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:06:47

20MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:08:59

20MHz_Middle_QPSK_1@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:09:36


20MHz_High_QPSK_1@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 26.AUG.2024 20:10:13


B7 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 20:26:15

5MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 20:26:57

5MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 20:27:41

10MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 20:29:53

10MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 20:30:38

10MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 28.AUG.2024 20:31:22

15MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:33:34

15MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:34:18

15MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:35:01

20MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:37:21

20MHz_Middle_QPSK_1@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:38:08


20MHz_High_QPSK_1@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 26.AUG.2024 20:38:57


B38 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:06:58

5MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:07:37

5MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:08:01

10MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:10:10

10MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:10:38

10MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
Date: 29.AUG.2024 13:11:04

15MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:13:05

15MHz_Middle_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:13:34

15MHz_High_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:14:03

20MHz_Low_QPSK_1@0




ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:16:14

20MHz_Middle_QPSK_1@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:16:44

20MHz_High_QPSK_1@0



ProjectNo.:2402W90636E-RF Tester:Loge Long
 Date: 29.AUG.2024 13:17:16