



LTE Band 4, Normal


1.4MHz_Middle_QPSK_1@0




1.4MHz_Middle_QPSK_6@0




1.4MHz_Middle_16QAM_1@0




1.4MHz_Middle_16QAM_6@0




3MHz_Middle_QPSK_1@0




3MHz_Middle_QPSK_15@0




3MHz_Middle_16QAM_1@0




3MHz_Middle_16QAM_15@0




5MHz_Middle_QPSK_1@0




5MHz_Middle_QPSK_25@0




5MHz_Middle_16QAM_1@0



5MHz_Middle_16QAM_25@0




10MHz_Middle_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 21:59:46

10MHz_Middle_QPSK_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:00:09

10MHz_Middle_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:00:31

10MHz_Middle_16QAM_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:00:54

15MHz_Middle_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:01:24

15MHz_Middle_QPSK_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:01:46


15MHz_Middle_16QAM_1@0




15MHz_Middle_16QAM_75@0




20MHz_Middle_QPSK_1@0




20MHz_Middle_QPSK_100@0



20MHz_Middle_16QAM_1@0




20MHz_Middle_16QAM_100@0




LTE Band 7, Normal


5MHz_Middle_QPSK_1@0




5MHz_Middle_QPSK_25@0




5MHz_Middle_16QAM_1@0




5MHz_Middle_16QAM_25@0




10MHz_Middle_QPSK_1@0




10MHz_Middle_QPSK_50@0




10MHz_Middle_16QAM_1@0




10MHz_Middle_16QAM_50@0




15MHz_Middle_QPSK_1@0




15MHz_Middle_QPSK_75@0




15MHz_Middle_16QAM_1@0




15MHz_Middle_16QAM_75@0




20MHz_Middle_QPSK_1@0




20MHz_Middle_QPSK_100@0



20MHz_Middle_16QAM_1@0




20MHz_Middle_16QAM_100@0




LTE Band 38, Normal


5MHz_Middle_QPSK_1@0



5MHz_Middle_QPSK_25@0




5MHz_Middle_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 25.JUN.2025 18:16:29

5MHz_Middle_16QAM_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:22:17

10MHz_Middle_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:36:53

10MHz_Middle_QPSK_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:23:06

10MHz_Middle_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 25.JUN.2025 18:16:43

10MHz_Middle_16QAM_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:23:50

15MHz_Middle_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:37:56

15MHz_Middle_QPSK_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:30:07

15MHz_Middle_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:38:29

15MHz_Middle_16QAM_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:25:29

20MHz_Middle_QPSK_1@0



ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:39:00


20MHz_Middle_QPSK_100@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:39:25

20MHz_Middle_16QAM_1@0

20MHz_Middle_16QAM_100@0



ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 25.JUN.2025 18:16:57




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 23.JUN.2025 22:29:22

Out of band emission,Band Edge


FCC Part 22H

LTE Band 5, Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0



1.4MHz_High_QPSK_1@5




1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5

1.4MHz_High_16QAM_6@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:58:22




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:59:10

3MHz_Low_QPSK_1@0

3MHz_Low_QPSK_15@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:03:17




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:04:13

3MHz_Low_16QAM_1@0

3MHz_Low_16QAM_15@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:05:09




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:06:05

3MHz_High_QPSK_1@14




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:07:00

3MHz_High_QPSK_15@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:07:57

3MHz_High_16QAM_1@14




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:08:54

3MHz_High_16QAM_15@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:09:51

5MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 22:11:41

5MHz_Low_QPSK_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:24:29

5MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:25:29

5MHz_Low_16QAM_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:26:30

5MHz_High_QPSK_1@24




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 22:12:45

5MHz_High_QPSK_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:28:28

5MHz_High_16QAM_1@24




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:29:26

5MHz_High_16QAM_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:30:24

10MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 22:16:00

10MHz_Low_QPSK_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:34:36

10MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 22:17:25

10MHz_Low_16QAM_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:37:15

10MHz_High_QPSK_1@49




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:38:36

10MHz_High_QPSK_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:39:57

10MHz_High_16QAM_1@49



ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:41:18

10MHz_High_16QAM_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:42:40

FCC Part 24E


LTE Band 2, Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:42:01

1.4MHz_Low_QPSK_6@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:42:28

1.4MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:42:56

1.4MHz_Low_16QAM_6@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:43:23

1.4MHz_High_QPSK_1@5




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:44:01

1.4MHz_High_QPSK_6@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:44:40

1.4MHz_High_16QAM_1@5




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:45:08

1.4MHz_High_16QAM_6@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:45:36

3MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:48:14

3MHz_Low_QPSK_15@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:48:46

3MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:49:18

3MHz_Low_16QAM_15@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:49:50

3MHz_High_QPSK_1@14




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:50:22

3MHz_High_QPSK_15@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:50:54

3MHz_High_16QAM_1@14




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:51:26

3MHz_High_16QAM_15@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:51:57

5MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:53:48

5MHz_Low_QPSK_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:54:17

5MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:58:09

5MHz_Low_16QAM_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:58:39

5MHz_High_QPSK_1@24




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:59:09

5MHz_High_QPSK_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 17:59:38

5MHz_High_16QAM_1@24



ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:00:08

5MHz_High_16QAM_25@0



ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:00:38