



10MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:02:11

10MHz_Low_QPSK_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:02:51

10MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:03:31

10MHz_Low_16QAM_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:04:10

10MHz_High_QPSK_1@49




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:04:50

10MHz_High_QPSK_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:05:28

10MHz_High_16QAM_1@49




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:06:07

10MHz_High_16QAM_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:06:45

15MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:21:56

15MHz_Low_QPSK_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:19:54

15MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:22:46

15MHz_Low_16QAM_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:23:36

15MHz_High_QPSK_1@74




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:24:27

15MHz_High_QPSK_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:25:17

15MHz_High_16QAM_1@74




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:26:08

15MHz_High_16QAM_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:26:59

20MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:28:26

20MHz_Low_QPSK_100@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:29:26

20MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:30:26

20MHz_Low_16QAM_100@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:31:26

20MHz_High_QPSK_1@99




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 25.JUN.2025 23:13:10

20MHz_High_QPSK_100@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:33:44

20MHz_High_16QAM_1@99



ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 25.JUN.2025 23:28:57

20MHz_High_16QAM_100@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:35:44


FCC Part 27

LTE Band 4, Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0



1.4MHz_High_QPSK_1@5




1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5

1.4MHz_High_16QAM_6@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:40:10




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:40:39

3MHz_Low_QPSK_1@0

3MHz_Low_QPSK_15@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:41:54




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:42:26

3MHz_Low_16QAM_1@0

3MHz_Low_16QAM_15@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:42:59




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:43:32

3MHz_High_QPSK_1@14




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:44:06

3MHz_High_QPSK_15@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:44:39

3MHz_High_16QAM_1@14




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 22:03:19

3MHz_High_16QAM_15@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:45:45

5MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:46:19

5MHz_Low_QPSK_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:47:19

5MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:47:50

5MHz_Low_16QAM_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:48:20

5MHz_High_QPSK_1@24




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:48:51

5MHz_High_QPSK_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:49:22

5MHz_High_16QAM_1@24




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 22:04:55

5MHz_High_16QAM_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:50:22

10MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:51:44

10MHz_Low_QPSK_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:52:25

10MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:53:07

10MHz_Low_16QAM_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:53:48

10MHz_High_QPSK_1@49




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:54:30

10MHz_High_QPSK_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:55:12

10MHz_High_16QAM_1@49




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:55:55

10MHz_High_16QAM_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:56:38

15MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 22:06:25

15MHz_Low_QPSK_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 18:58:56

15MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 22:07:18

15MHz_Low_16QAM_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:00:41

15MHz_High_QPSK_1@74




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:01:34

15MHz_High_QPSK_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:02:27

15MHz_High_16QAM_1@74




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:03:19

15MHz_High_16QAM_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:04:11

20MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:34:46

20MHz_Low_QPSK_100@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:35:45

20MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:43:31

20MHz_Low_16QAM_100@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:45:15

20MHz_High_QPSK_1@99




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:48:36

20MHz_High_QPSK_100@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:49:36

20MHz_High_16QAM_1@99



ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 22:09:01


20MHz_High_16QAM_100@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 19:51:38

LTE Band 7, Normal


5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0




5MHz_Low_16QAM_25@0



5MHz_High_QPSK_1@24




5MHz_High_QPSK_25@0




5MHz_High_16QAM_1@24

5MHz_High_16QAM_25@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:46:21




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:46:53

10MHz_Low_QPSK_1@0

10MHz_Low_QPSK_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:47:57




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:48:16

10MHz_Low_16QAM_1@0

10MHz_Low_16QAM_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:48:36




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:48:56

10MHz_High_QPSK_1@49




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:49:19

10MHz_High_QPSK_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:50:00

10MHz_High_16QAM_1@49




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 22:20:22

10MHz_High_16QAM_50@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:51:21

15MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:52:29

15MHz_Low_QPSK_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:52:51

15MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 22:21:27

15MHz_Low_16QAM_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:53:37

15MHz_High_QPSK_1@74




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:54:03

15MHz_High_QPSK_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:54:56

15MHz_High_16QAM_1@74




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:55:19

15MHz_High_16QAM_75@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:56:42

20MHz_Low_QPSK_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:57:52

20MHz_Low_QPSK_100@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:58:13

20MHz_Low_16QAM_1@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:58:33

20MHz_Low_16QAM_100@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 20:58:55

20MHz_High_QPSK_1@99




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 22:23:18

20MHz_High_QPSK_100@0




ProjectNo.:2502T61980E-RF Tester:Loge Long
Date: 24.JUN.2025 21:00:22

20MHz_High_16QAM_1@99




20MHz_High_16QAM_100@0




LTE Band 38, Normal


5MHz_Low_QPSK_1@0



5MHz_Low_QPSK_25@0



5MHz_Low_16QAM_1@0



5MHz_Low_16QAM_25@0

