



Montpellier
December 20, 2019

Subject: Request for a Change in identification of equipment per 47 CFR 2.933 of the FCC rules.

Applicant: OCEASOFT

Model: OCEASOFT LoRMur Daughter Card

FCC ID: XTLCMABZ

To Whom It May Concern:

This multiple listing certification request applies for a new FCC ID as established in 2.933 for a currently approved device.

This application by **OCEASOFT** will establish a new FCC ID under **XTLCMABZ** Grantee code for the purpose of marketing.

The original FCC ID of **MURATA** FCC ID: **VPYCMABZ** will remain in effect.

An authorization letter by **MURATA** is attached.

Per 2.933

- 1) a -The original model number is: **CMWX1ZZABZ**
b -The original certification number is: FCC ID: **VPYCMABZ**
- 2) The original certification date is: **09/28/2018**
- 3) The equipment is identical in design and construction to the originally-approved model.
- 4) The original test results continue to be representative of and applicable to the equipment bearing the changed identification.
- 5) External photographs with FCC ID label location info are included in this application.

The following files are electronically submitted as attachments:

- External Photos
- ID Label info
- location info.

1/1

If you have any queries, please do not hesitate to contact us.
Regards,

Laurent Rousseau Managing Director, December 20, 2019

A handwritten signature in black ink, appearing to read "Laurent Rousseau".



OCEASOFT S.A.
720 Rue Louis Lépine
34000 Montpellier
FRANCE
contact@oceasoft.com
www.oceasoft.com

S.A. au capital de 289.462,50 euros
RCS Montpellier - SIREN: 425014180
TVA : FR56425014180
MKT-DOC-052-FR V01