

Date: August 6, 2018

Federal Communications Commission

Authorization and Evaluation Division

7435 Oakland Mills Rd

Columbia MD 21046-1609

Subject: Request to change in Identification

To Whom It May Concern:

This application for Change of Identification request a new FCC ID as stipulated in 47CFR 2.933(b) for presently authorized equipment.

This application by TRENDNET, Inc. will establish a new FCC ID under FCC ID: **XU8TEW648UBMV2** for the purpose of marketing.

The original grant to Edimax Technology Co Ltd, FCC ID: **ND9578111008** will remain in effect.

Per 2.933(b)

- (1) The original identification is FCC ID: **ND9578111008**
- (2) The original grant date is **04/16/2010**
- (3) The equipment is electrically and functionally identical. Only the **model name, trade name** and **FCC ID number** are different.
- (4) The original test results are applicable and representative of this changed device.

Sincerely yours,

Applicant : TRENDNET, Inc.
Address : 20675 Manhattan Place Torrance California 90501 United States

Signature

A handwritten signature in blue ink, appearing to read "Nevin".



Name and Job Title. : Wen Tsai, Sr. Product Manager

E-mail : w.tsai@trendnet.com

Tel. : 310-961-5500 EX5474