


Job No.:160121-Dbii-5250

Date:2016-01-21

Time:15:05

Tested by: John

Center freq.(MHz): : 5250




Job No.:160121-Dbii-5310

Date:2016-01-21

Time:15:05

Tested by: John

Center freq.(MHz): : 5310




Job No.:160121-Dbii-5320

Date:2016-01-21

Time:15:05

Tested by: John

Center freq.(MHz): : 5320




Job No.:160121-Dbii-5330

Date:2016-01-21

Time:15:05

Tested by: John

Center freq.(MHz): : 5330




Job No.:160121-Dbii-5550

Date:2016-01-21

Time:15:05

Tested by: John

Center freq.(MHz): : 5550




Job No.:160121-Dbii-5725

Date:2016-01-21

Time:15:05

Tested by: John

Center freq.(MHz): : 5725



Job No.:160121-Dbii-5850

Date:2016-01-21

Time:15:05

Tested by: John

Center freq.(MHz): : 5850

