

**INTERTEK TESTING SERVICE**

---


Report No: HK11060153-3

**Configuration Photographs**

**Worst-Case Line-Conducted Emissions**

**(Front View)**

**Model : X Mark I Keypad RF**



# INTERTEK TESTING SERVICE


Report No: HK11060153-3

## Configuration Photographs

### Worst-Case Line-Conducted Emissions

(Back View)

**Model : X Mark I Keypad RF**



# INTERTEK TESTING SERVICE

Report No: HK11060153-3

## Configuration Photographs

### Worst-Case Line-Conducted Emissions

(Side View)

**Model : X Mark I Keypad RF**

