



INTERTEK TESTING SERVICES

Report No.: HK11060153-4

Sample No.: 1/2 (Keypad)



Bandedge Plot – Pursuant to FCC Part 15 Section 15. 249 Requirement