

## Tune-up procedure

### 1-1、 Power

1. Connect to ANT to Spectrum Analyzer
2. Adjust VC 103 , Make the main wave biggest ;
3. Adjust T2、 T3、 T4 ,
4. SPEC: The radiation of wave in harmony is lower than the above main wave 40dB.  
The main wave does not exceed 50Mw.

### 1-2、 Frequency adjustment

1. Connect ANT to Modulation Meter)
2. Adjust I1
3. SPEC : Frequency +-20KHz.

### 1-3、 TONE KEY modulation adjustment

1. Connect ANT to Multifunction Counter;
2. Connect MIC to Audio Analyzer :1KHz,30db
3. Adjust VR ;
4. SPEC : 30KHz , +-1KHz