

## Audit Mode Request Letter

TIMCO Engineering, Inc.

This is to request audit mode of FCC ID: YHLBLUB110DL,

RF output power, radiated spurious emission and radiated band-edge were verified and retested by JianYan Testing Group Shenzhen Co., Ltd.

The EUT is operating at the same power level with the original testing of SGS-CSTC Standards Technical Services, Co., Ltd. Shenzhen Branch.


Other data are referred from the original reports issued by SGS-CSTC Standards Technical Services, Co., Ltd. Shenzhen Branch.

All the test detail data in the test reports which we will upload after audit mode.

The major change filed under this application and the relevant report numbers are as below:

Equipment class	Original report number	Date of test	Retest report number	Date of test for retest items	Revise content
PCE	ZR/2019/A000601	2019/10/17 ~2019/10/31	JYTSZB-R12-2102952, JYTSZB-R12-2102953, JYTSZB-R12-2102954	2021/12/10 ~2022/1/15	1. Retest the Field Strength of Spurious Radiation 2. Verify RF output power
DTS	ZR/2019/A000602	2019/10/17 ~2019/10/31	JYTSZB-R12-2102956	2021/12/10 ~2022/1/15	1. Retest the radiated spurious emission and Radiated band-edge. 2. Verify RF output power
DTS	ZR/2019/A000603	2019/10/17 ~2019/10/31	JYTSZB-R12-2102955	2021/12/10 ~2022/1/15	1. Retest the radiated spurious emission and Radiated band-edge. 2. Verify RF output power
DSS	ZR/2019/A000604	2019/10/17 ~2019/10/31	JYTSZB-R12-2102957	2021/12/10 ~2022/1/15	1. Retest the radiated spurious emission and Radiated band-edge. 2. Verify RF output power

Sincerely,



(signature)

(printed name) Derek Yang