



Please refer to following plots:




Date: 13.MAR.2021 15:49:45




Date: 13.MAR.2021 15:50:07

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 13.MAR.2021 15:50:27

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 13.MAR.2021 15:50:43

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 13.MAR.2021 15:51:05

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 13.MAR.2021 15:51:21

Band 2_3 MHz_High_QPSK_RB15#0




Date: 13.MAR.2021 15:51:37

Band 2_3 MHz_High_16QAM_RB15#0




Date: 13.MAR.2021 15:51:53

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 13.MAR.2021 16:36:26

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 13.MAR.2021 16:37:33

Band 2_5 MHz_High_QPSK_RB25#0




Date: 13.MAR.2021 16:38:25

Band 2_5 MHz_High_16QAM_RB25#0




Date: 13.MAR.2021 15:53:09

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 13.MAR.2021 15:53:30

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 13.MAR.2021 15:53:47

Band 2_10 MHz_High_QPSK_RB50#0




Date: 13.MAR.2021 15:54:07

Band 2_10 MHz_High_16QAM_RB50#0




Date: 13.MAR.2021 15:54:24

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 13.MAR.2021 16:39:59

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 13.MAR.2021 16:40:29

Band 2_15 MHz_High_QPSK_RB75#0




Date: 13.MAR.2021 16:41:24

Band 2_15 MHz_High_16QAM_RB75#0




Date: 13.MAR.2021 16:42:10

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 13.MAR.2021 15:56:08

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 13.MAR.2021 15:56:30

Band 2_20 MHz_High_QPSK_RB100#0




Date: 13.MAR.2021 15:56:53

Band 2_20 MHz_High_16QAM_RB100#0




Date: 13.MAR.2021 15:57:12

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 13.MAR.2021 15:57:34

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 13.MAR.2021 15:57:56

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 13.MAR.2021 15:58:13

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 13.MAR.2021 15:58:28

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 13.MAR.2021 15:58:48

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 13.MAR.2021 15:59:06

Band 4_3 MHz_High_QPSK_RB15#0




Date: 13.MAR.2021 15:59:23

Band 4_3 MHz_High_16QAM_RB15#0




Date: 13.MAR.2021 15:59:38

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 13.MAR.2021 15:59:58

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 13.MAR.2021 16:00:20

Band 4_5 MHz_High_QPSK_RB25#0




Date: 13.MAR.2021 16:45:04

Band 4_5 MHz_High_16QAM_RB25#0




Date: 13.MAR.2021 16:00:58

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 13.MAR.2021 16:01:19

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 13.MAR.2021 16:01:35

Band 4_10 MHz_High_QPSK_RB50#0




Date: 13.MAR.2021 16:01:53

Band 4_10 MHz_High_16QAM_RB50#0




Date: 13.MAR.2021 16:02:10

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 13.MAR.2021 16:02:33

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 13.MAR.2021 16:47:06

Band 4_15 MHz_High_QPSK_RB75#0




Date: 13.MAR.2021 16:48:10

Band 4_15 MHz_High_16QAM_RB75#0




Date: 13.MAR.2021 16:48:32

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 13.MAR.2021 16:03:57

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 13.MAR.2021 16:04:19

Band 4_20 MHz_High_QPSK_RB100#0




Date: 13.MAR.2021 16:04:42

Band 4_20 MHz_High_16QAM_RB100#0




Date: 13.MAR.2021 16:05:01

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 13.MAR.2021 16:05:21

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 13.MAR.2021 16:05:40

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 13.MAR.2021 16:05:59

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 13.MAR.2021 16:06:18

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 13.MAR.2021 16:06:38

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 13.MAR.2021 16:06:53

Band 5_3 MHz_High_QPSK_RB15#0




Date: 13.MAR.2021 16:07:10

Band 5_3 MHz_High_16QAM_RB15#0




Date: 13.MAR.2021 16:07:28

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 13.MAR.2021 16:50:03

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 13.MAR.2021 16:08:04

Band 5_5 MHz_High_QPSK_RB25#0




Date: 13.MAR.2021 16:08:20

Band 5_5 MHz_High_16QAM_RB25#0




Date: 13.MAR.2021 16:08:36

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 13.MAR.2021 16:08:56

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 13.MAR.2021 16:09:13

Band 5_10 MHz_High_QPSK_RB50#0




Date: 13.MAR.2021 16:09:31

Band 5_10 MHz_High_16QAM_RB50#0




Date: 13.MAR.2021 16:09:47

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 13.MAR.2021 16:51:13

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 13.MAR.2021 16:51:43

Band 7_5 MHz_High_QPSK_RB25#0




Date: 13.MAR.2021 16:52:25

Band 7_5 MHz_High_16QAM_RB25#0




Date: 13.MAR.2021 16:52:52

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 13.MAR.2021 16:11:21

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 13.MAR.2021 16:11:38

Band 7_10 MHz_High_QPSK_RB50#0




Date: 13.MAR.2021 16:11:55

Band 7_10 MHz_High_16QAM_RB50#0




Date: 13.MAR.2021 16:12:12

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 13.MAR.2021 16:53:41

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 13.MAR.2021 16:54:11

Band 7_15 MHz_High_QPSK_RB75#0




Date: 13.MAR.2021 16:55:02

Band 7_15 MHz_High_16QAM_RB75#0




Date: 13.MAR.2021 16:55:29

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 13.MAR.2021 16:13:59

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 13.MAR.2021 16:14:21

Band 7_20 MHz_High_QPSK_RB100#0




Date: 13.MAR.2021 16:14:41

Band 7_20 MHz_High_16QAM_RB100#0




Date: 13.MAR.2021 16:15:00

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 13.MAR.2021 16:15:25

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 13.MAR.2021 16:15:41

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 13.MAR.2021 16:15:57

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 13.MAR.2021 16:16:16

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 13.MAR.2021 16:16:36

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 13.MAR.2021 16:16:54

Band 12_3 MHz_High_QPSK_RB15#0




Date: 13.MAR.2021 16:17:14

Band 12_3 MHz_High_16QAM_RB15#0




Date: 13.MAR.2021 16:17:33

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 13.MAR.2021 16:17:55

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 13.MAR.2021 16:18:14

Band 12_5 MHz_High_QPSK_RB25#0




Date: 13.MAR.2021 16:18:31

Band 12_5 MHz_High_16QAM_RB25#0




Date: 13.MAR.2021 17:01:00

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 13.MAR.2021 16:19:10

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 13.MAR.2021 16:19:27

Band 12_10 MHz_High_QPSK_RB50#0




Date: 13.MAR.2021 16:19:45

Band 12_10 MHz_High_16QAM_RB50#0




Date: 13.MAR.2021 16:20:01

Please refer to following plots:




Date: 24.MAR.2021 16:33:45




Date: 24.MAR.2021 16:34:07

Band 38_5 MHz_High_QPSK_RB25#0




Date: 24.MAR.2021 16:34:26

Band 38_5 MHz_High_16QAM_RB25#0




Date: 24.MAR.2021 16:34:45

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 24.MAR.2021 16:35:08

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 24.MAR.2021 16:35:27

Band 38_10 MHz_High_QPSK_RB50#0




Date: 24.MAR.2021 16:35:48

Band 38_10 MHz_High_16QAM_RB50#0




Date: 24.MAR.2021 16:36:04

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 24.MAR.2021 16:36:29

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 24.MAR.2021 16:36:52

Band 38_15 MHz_High_QPSK_RB75#0




Date: 24.MAR.2021 16:37:11

Band 38_15 MHz_High_16QAM_RB75#0




Date: 24.MAR.2021 16:37:36

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 24.MAR.2021 16:37:59

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 24.MAR.2021 16:38:21

Band 38_20 MHz_High_QPSK_RB100#0



Date: 24.MAR.2021 16:38:40

Band 38_20 MHz_High_16QAM_RB100#0



Date: 24.MAR.2021 16:39:02