





Band4_1.4MHz_QPSK_20175_1RB#0_3000~20000_00_3000~20000


Band4_1.4MHz_16QAM_20175_1RB#0_0.009~0.15_15_0.009~0.15




Band4_1.4MHz_16QAM_20175_1RB#0_0.15~30_0.15~30


Band4_1.4MHz_16QAM_20175_1RB#0_30~1000_30~1000








Date: 8.MAY.2024 22:30:31




Date: 8.MAY.2024 22:30:40

Band4_1.4MHz_QPSK_20393_1RB#0_3000~20000

Band4_1.4MHz_16QAM_20393_1RB#0_0.009~0.15




Date: 8.MAY.2024 22:30:48




Date: 8.MAY.2024 22:30:57

Band4_1.4MHz_16QAM_20393_1RB#0_0.15~30


Band4_1.4MHz_16QAM_20393_1RB#0_30~1000




Date: 8.MAY.2024 22:31:06




Date: 8.MAY.2024 22:31:15






Date: 8.MAY.2024 22:58:19




Date: 8.MAY.2024 22:58:28

Band4_3MHz_QPSK_19965_1RB#0_3000~2000
0_3000~20000

Band4_3MHz_16QAM_19965_1RB#0_0.009~0.15
_0.009~0.15




Date: 8.MAY.2024 22:58:37




Date: 8.MAY.2024 22:58:46

Band4_3MHz_16QAM_19965_1RB#0_0.15~30
0.15~30

Band4_3MHz_16QAM_19965_1RB#0_30~1000_3
0~1000



Date: 8.MAY.2024 22:58:54



Date: 8.MAY.2024 22:59:03