




Band4_15MHz_QPSK_20025_1RB#0_3000~20000_00_3000~20000




Band4_15MHz_16QAM_20025_1RB#0_0.009~0.15_5_0.009~0.15




Band4_15MHz_16QAM_20025_1RB#0_0.15~30_0.15~30




Band4_15MHz_16QAM_20025_1RB#0_30~1000_30~1000




Band4_15MHz_QPSK_20025_1RB#0_3000~20000_00_3000~20000




Band4_15MHz_16QAM_20025_1RB#0_30~1000_30~1000






Date: 9.MAY.2024 00:34:11




Date: 9.MAY.2024 00:34:21

Band4_15MHz_QPSK_20175_1RB#0_3000~20000_3000~20000

Band4_15MHz_16QAM_20175_1RB#0_0.009~0.15_5_0.009~0.15




Date: 9.MAY.2024 00:34:29




Date: 9.MAY.2024 00:34:38

Band4_15MHz_16QAM_20175_1RB#0_0.15~30_0.15~30

Band4_15MHz_16QAM_20175_1RB#0_30~1000_30~1000



Date: 9.MAY.2024 00:34:47



Date: 9.MAY.2024 00:34:56