




Band4_15MHz_QPSK_20325_1RB#0_3000~20000_00_3000~20000




Band4_15MHz_16QAM_20325_1RB#0_0.009~0.15_5_0.009~0.15




Band4_15MHz_16QAM_20325_1RB#0_0.15~30_0.15~30




Band4_15MHz_16QAM_20325_1RB#0_30~1000_30~1000




Band4_15MHz_QPSK_20325_1RB#0_3000~20000_00_3000~20000




Band4_15MHz_16QAM_20325_1RB#0_30~1000_30~1000






Date: 9.MAY.2024 01:04:30




Date: 9.MAY.2024 01:04:39

Band4_20MHz_QPSK_20050_1RB#0_3000~2000_3000~20000

Band4_20MHz_16QAM_20050_1RB#0_0.009~0.15_0.009~0.15




Date: 9.MAY.2024 01:04:48




Date: 9.MAY.2024 01:04:57

Band4_20MHz_16QAM_20050_1RB#0_0.15~30_0.15~30

Band4_20MHz_16QAM_20050_1RB#0_30~1000_30~1000



Date: 9.MAY.2024 01:05:05



Date: 9.MAY.2024 01:05:14

