



Date: 9.MAY.2024 09:42:14




Date: 9.MAY.2024 09:42:23

Band5_1.4MHz_QPSK_20643_1RB#0_3000~10000

Band5_1.4MHz_16QAM_20643_1RB#0_0.009~0.15




Date: 9.MAY.2024 09:42:32




Date: 9.MAY.2024 09:42:41

Band5_1.4MHz_16QAM_20643_1RB#0_0.15~30


Band5_1.4MHz_16QAM_20643_1RB#0_30~1000





Date: 9.MAY.2024 09:42:49





Date: 9.MAY.2024 09:42:58











Band5_3MHz_QPSK_20525_1RB#0_3000~1000
 0_3000~10000

Band5_3MHz_16QAM_20525_1RB#0_0.009~0.15
 0_009~0.15



Band5_3MHz_16QAM_20525_1RB#0_0.15~30
 0.15~30

Band5_3MHz_16QAM_20525_1RB#0_30~1000_3
 0~1000

