



Date: 9.MAY.2024 10:14:05




Date: 9.MAY.2024 10:14:15

Band5\_3MHz\_QPSK\_20635\_1RB#0\_3000~1000  
0\_3000~10000

Band5\_3MHz\_16QAM\_20635\_1RB#0\_0.009~0.15  
\_0.009~0.15




Date: 9.MAY.2024 10:14:23




Date: 9.MAY.2024 10:14:32

Band5\_3MHz\_16QAM\_20635\_1RB#0\_0.15~30  
0.15~30


Band5\_3MHz\_16QAM\_20635\_1RB#0\_30~1000\_3  
0~1000





Date: 9.MAY.2024 10:14:40





Date: 9.MAY.2024 10:14:49





Band5\_5MHz\_QPSK\_20425\_1RB#0\_3000~1000  
0\_3000~10000

Band5\_5MHz\_16QAM\_20425\_1RB#0\_0.009~0.15  
\_0.009~0.15



Band5\_5MHz\_16QAM\_20425\_1RB#0\_0.15~30  
0.15~30

Band5\_5MHz\_16QAM\_20425\_1RB#0\_30~1000\_3  
0~1000

