



Date: 9.MAY.2024 12:55:49




Date: 9.MAY.2024 12:55:59

Band7_15MHz_QPSK_20825_1RB#0_20000~27000

Band7_15MHz_16QAM_20825_1RB#0_0.009~0.1




Date: 9.MAY.2024 12:56:07




Date: 9.MAY.2024 12:56:16

Band7_15MHz_16QAM_20825_1RB#0_0.15~30


Band7_15MHz_16QAM_20825_1RB#0_30~1000




Date: 9.MAY.2024 12:56:25




Date: 9.MAY.2024 12:56:37






Date: 9.MAY.2024 12:57:27




Date: 9.MAY.2024 12:57:36

Band7_15MHz_QPSK_21100_1RB#0_20000~27000_000_20000~27000

Band7_15MHz_16QAM_21100_1RB#0_0.009~0.15_0.009~0.15




Date: 9.MAY.2024 12:57:45




Date: 9.MAY.2024 12:57:54

Band7_15MHz_16QAM_21100_1RB#0_0.15~30_0.15~30

Band7_15MHz_16QAM_21100_1RB#0_30~1000_30~1000



Date: 9.MAY.2024 12:58:03



Date: 9.MAY.2024 12:58:15

