



Date: 9.MAY.2024 14:42:04




Date: 9.MAY.2024 14:42:13

Band12\_1.4MHz\_QPSK\_23173\_1RB#0\_3000~10000

Band12\_1.4MHz\_16QAM\_23173\_1RB#0\_0.009~0.15




Date: 9.MAY.2024 14:42:22




Date: 9.MAY.2024 14:42:31

Band12\_1.4MHz\_16QAM\_23173\_1RB#0\_0.15~30


Band12\_1.4MHz\_16QAM\_23173\_1RB#0\_30~100





Date: 9.MAY.2024 14:42:40





Date: 9.MAY.2024 14:42:49







Band12\_3MHz\_QPSK\_23025\_1RB#0\_3000~10000


Band12\_3MHz\_16QAM\_23025\_1RB#0\_0.009~0.15





Band12\_3MHz\_16QAM\_23025\_1RB#0\_0.15~30

Band12\_3MHz\_16QAM\_23025\_1RB#0\_30~1000









Band12\_3MHz\_QPSK\_23095\_1RB#0\_3000~10000

Band12\_3MHz\_16QAM\_23095\_1RB#0\_0.009~0.15  
5\_0.009~0.15



Band12\_3MHz\_16QAM\_23095\_1RB#0\_0.15~30  
0.15~30

Band12\_3MHz\_16QAM\_23095\_1RB#0\_30~1000  
30~1000

