



Date: 9.MAY.2024 15:14:26




Date: 9.MAY.2024 15:14:35

Band12_3MHz_QPSK_23165_1RB#0_3000~10000_00_3000~10000

Band12_3MHz_16QAM_23165_1RB#0_0.009~0.15_5_0.009~0.15




Date: 9.MAY.2024 15:14:44




Date: 9.MAY.2024 15:14:53

Band12_3MHz_16QAM_23165_1RB#0_0.15~30_0.15~30


Band12_3MHz_16QAM_23165_1RB#0_30~1000_30~1000




Date: 9.MAY.2024 15:15:01




Date: 9.MAY.2024 15:15:10






Date: 9.MAY.2024 15:44:45




Date: 9.MAY.2024 15:44:55

Band12_5MHz_QPSK_23035_1RB#0_3000~10000

Band12_5MHz_16QAM_23035_1RB#0_0.009~0.15




Date: 9.MAY.2024 15:45:03




Date: 9.MAY.2024 15:45:12

Band12_5MHz_16QAM_23035_1RB#0_0.15~30

Band12_5MHz_16QAM_23035_1RB#0_30~1000



Date: 9.MAY.2024 15:45:21



Date: 9.MAY.2024 15:45:30

