



Date: 9.MAY.2024 17:45:57




Date: 9.MAY.2024 17:46:06

Band17_5MHz_QPSK_23790_1RB#0_3000~10000

Band17_5MHz_16QAM_23790_1RB#0_0.009~0.15




Date: 9.MAY.2024 17:46:15




Date: 9.MAY.2024 17:46:24

Band17_5MHz_16QAM_23790_1RB#0_0.15~30


Band17_5MHz_16QAM_23790_1RB#0_30~1000




Date: 9.MAY.2024 17:46:32




Date: 9.MAY.2024 17:46:41






Date: 9.MAY.2024 17:47:28




Date: 9.MAY.2024 17:47:37

Band17_5MHz_QPSK_23825_1RB#0_3000~10000

Band17_5MHz_16QAM_23825_1RB#0_0.009~0.15




Date: 9.MAY.2024 17:47:46




Date: 9.MAY.2024 17:47:54

Band17_5MHz_16QAM_23825_1RB#0_0.15~30


Band17_5MHz_16QAM_23825_1RB#0_30~1000





Date: 9.MAY.2024 17:48:03





Date: 9.MAY.2024 17:48:12





Band17_10MHz_QPSK_23780_1RB#0_3000~10000

Band17_10MHz_16QAM_23780_1RB#0_0.009~0.15



Band17_10MHz_16QAM_23780_1RB#0_0.15~3

Band17_10MHz_16QAM_23780_1RB#0_30~1000

