



Date: 10.MAY.2024 21:42:53




Date: 10.MAY.2024 21:43:28

Band41_10MHz_QPSK_40620_1RB#0_20000~27000

Band41_10MHz_16QAM_40620_1RB#0_0.009~0.15




Date: 10.MAY.2024 21:43:48




Date: 10.MAY.2024 21:44:09

Band41_10MHz_16QAM_40620_1RB#0_0.15~30


Band41_10MHz_16QAM_40620_1RB#0_30~1000




Date: 10.MAY.2024 21:44:30




Date: 10.MAY.2024 21:44:55






Date: 10.MAY.2024 21:46:59

Band41_10MHz_QPSK_41540_1RB#0_20000~27000_20000~27000




Date: 10.MAY.2024 21:47:34

Band41_10MHz_16QAM_41540_1RB#0_0.009~0.15_15_0.009~0.15




Date: 10.MAY.2024 21:47:55

Band41_10MHz_16QAM_41540_1RB#0_0.15~30_0_0.15~30




Date: 10.MAY.2024 21:48:16

Band41_10MHz_16QAM_41540_1RB#0_30~1000_30~1000



Date: 10.MAY.2024 21:48:37



Date: 10.MAY.2024 21:49:01

