



Date: 10.MAY.2024 01:11:31




Date: 10.MAY.2024 01:11:39

Band66_5MHz_QPSK_131997_1RB#0_30~1000_30~1000

Band66_5MHz_QPSK_131997_1RB#0_1000~3000_0_1000~3000




Date: 10.MAY.2024 01:11:48




Date: 10.MAY.2024 01:11:58

Band66_5MHz_QPSK_131997_1RB#0_3000~20000_000_3000~20000


Band66_5MHz_16QAM_131997_1RB#0_0.009~0.15_15_0.009~0.15




Date: 10.MAY.2024 01:12:06




Date: 10.MAY.2024 01:12:15






Date: 10.MAY.2024 01:13:02

Band66_5MHz_QPSK_132322_1RB#0_30~1000_30~1000




Date: 10.MAY.2024 01:13:11

Band66_5MHz_QPSK_132322_1RB#0_1000~3000_0_1000~3000




Date: 10.MAY.2024 01:13:20

Band66_5MHz_QPSK_132322_1RB#0_3000~20000_000_3000~20000




Date: 10.MAY.2024 01:13:30


Band66_5MHz_16QAM_132322_1RB#0_0.009~0.15_15_0.009~0.15




Date: 10.MAY.2024 01:13:38




Date: 10.MAY.2024 01:13:47






Date: 10.MAY.2024 01:14:34




Date: 10.MAY.2024 01:14:43

Band66_5MHz_QPSK_132647_1RB#0_30~1000_30~1000

Band66_5MHz_QPSK_132647_1RB#0_1000~3000_0_1000~3000




Date: 10.MAY.2024 01:14:52




Date: 10.MAY.2024 01:15:02

Band66_5MHz_QPSK_132647_1RB#0_3000~20000_000_3000~20000

Band66_5MHz_16QAM_132647_1RB#0_0.009~0.15_15_0.009~0.15



Date: 10.MAY.2024 01:15:10



Date: 10.MAY.2024 01:15:20