



INTERTEK TESTING SERVICES

Report No.: HK11090798-3
Sample No.: 1/2



Date: 7.DEC.2011 14:59:03



Date: 7.DEC.2011 14:50:08

Timing Plot – Pursuant to FCC Part 15 Section 15. 231(e) Requirement (Pass/Fail)