

# Sporton International Inc.

No.52, HwaYa 1st Rd., Kwei-Shan Hsiang, , Taoyuan Hsien 333, Taiwan, R.O.C.

Tel: 886-3-327-3456 ; Fax: 886-3-328-4978

## Declaration

**Date: September 14, 2011**

To whom it may concern,

The FCC qualified radio module ( FCC ID: **N7NMC8790**) is plugged in the our host product (model: **DLI8800**). It makes the host product with same configurations in the radio feature. The only one change is antenna between radio module and host so that conducted radio test item is re-used from the original module data and re-test ERP/ERIP/RSE for the host again only.

The test report information as below:

1. The test report No. is 08U11743-1
2. The Sierra Wireless report date is Apr. 29. 2008
3. The Sierra Wireless report date is Dec. 01. 2008

Sincerely yours,

**Duty Signature:**



**Contact Person:** Jones Tsai

**Company:** Sporton International Inc.

**TEL:** 886-3-327-3456

**FAX:** 886-3-328-4978

**E-mail:** JonesTsai@sporton.com.tw