



802.11ac40_5270MHz_Chain 0 41.341MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 17:51:06

802.11ac40_5310MHz_Chain 0 62.242MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 17:58:11

802.11ac40_5270MHz_Chain 1 40.641MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:37:07

802.11ac40_5310MHz_Chain 1 44.344MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:39:23

802.11ac40_5270MHz_Chain 2 40.641MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:27:35

802.11ac40_5310MHz_Chain 2 52.365MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:28:51

802.11ac80_5290MHz_Chain 0 102.707MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 17:59:47

802.11ac80_5290MHz_Chain 1 105.883MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:40:53

802.11ac80_5290MHz_Chain 2 105.171MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:30:40

802.11ax160_5250MHz_RU_Full_Chain 0 163.363MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:23:33

802.11ax160_5250MHz_RU_Full_Chain 1 164.565MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:54:16

802.11ax160_5250MHz_RU_Full_Chain 2 163.764MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:48:03

802.11ax20_5260MHz_RU_Full_Chain 0
22.399MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:13:42

802.11ax20_5280MHz_RU_Full_Chain 0
22.624MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:14:59

802.11ax20_5320MHz_RU_Full_Chain 0
29.537MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:16:19

802.11ax20_5260MHz_RU_Full_Chain 1
21.685MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:45:49

802.11ax20_5280MHz_RU_Full_Chain 1
22.038MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:47:18

802.11ax20_5320MHz_RU_Full_Chain 1
28.059MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:48:47

802.11ax20_5260MHz_RU_Full_Chain 2
22.233MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:33:40

802.11ax20_5280MHz_RU_Full_Chain 2
22.088MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:38:39

802.11ax20_5320MHz_RU_Full_Chain 2
27.136MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:41:17

802.11ax40_5270MHz_RU_Full_Chain 0
39.940MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:17:45

802.11ax40_5310MHz_RU_Full_Chain 0
49.650MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:18:47

802.11ax40_5270MHz_RU_Full_Chain 1
39.840MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:50:11

802.11ax40_5310MHz_RU_Full_Chain 1
50.702MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:51:35

802.11ax40_5270MHz_RU_Full_Chain 2
39.840MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:43:23

802.11ax40_5310MHz_RU_Full_Chain 2
49.249MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:45:05

802.11ax80_5290MHz_RU_Full_Chain 0
92.292MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:21:06

802.11ax80_5290MHz_RU_Full_Chain 1
81.481MHz



ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:52:51


802.11ax80_5290MHz_RU_Full_Chain 2
96.296MHz



ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:46:35


5470-5725MHz

802.11a_5500MHz_Chain 0 29.598MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 14:55:14

802.11a_5580MHz_Chain 0 31.548MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 14:57:46

802.11a_5700MHz_Chain 0 28.313MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 14:59:19

802.11a_5720MHz_Chain 0 37.323MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 15:00:40

802.11a_5500MHz_Chain 1 29.853MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 15:49:48

802.11a_5580MHz_Chain 1 34.376MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 15:51:24

802.11a_5700MHz_Chain 1 28.450MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 15:53:21

802.11a_5720MHz_Chain 1 34.630MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 15:54:47

802.11a_5500MHz_Chain 2 29.736MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 16:22:41

802.11a_5580MHz_Chain 2 33.885MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 16:24:32

802.11a_5700MHz_Chain 2 24.480MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 16:27:33

802.11a_5720MHz_Chain 2 26.501MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 16:29:03

802.11ac160_5570MHz_Chain 0 168.969MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 10:46:15

802.11ac160_5570MHz_Chain 1 170.571MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:37:58

802.11ac160_5570MHz_Chain 2 164.565MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:10:20

802.11ac20_5500MHz_Chain 0 28.464MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 10:27:58

802.11ac20_5580MHz_Chain 0 21.864MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 10:31:01

802.11ac20_5700MHz_Chain 0 28.201MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 10:32:17

802.11ac20_5720MHz_Chain 0 22.339MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 10:34:04

802.11ac20_5500MHz_Chain 1 27.630MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:58:08

802.11ac20_5580MHz_Chain 1 21.301MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 10:59:32

802.11ac20_5700MHz_Chain 1 27.067MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:13:40

802.11ac20_5720MHz_Chain 1 21.515MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:17:32

802.11ac20_5500MHz_Chain 2 28.900MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:50:35

802.11ac20_5580MHz_Chain 2 21.502MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:52:05

802.11ac20_5700MHz_Chain 2 27.995MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai
Date: 6.DEC.2024 14:53:50

802.11ac20_5720MHz_Chain 2 21.689MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:55:18

802.11ac40_5510MHz_Chain 0 58.669MHz




ProjectNo.:2401Y27848E-RF Testerr:Allen Bai
Date: 5.DEC.2024 18:38:20

802.11ac40_5550MHz_Chain 0 41.241MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:39:08

802.11ac40_5670MHz_Chain 0 65.547MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:40:32

802.11ac40_5710MHz_Chain 0 41.041MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 10:41:15

802.11ac40_5510MHz_Chain 1 45.946MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:18:40

802.11ac40_5550MHz_Chain 1 40.841MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:19:29

802.11ac40_5670MHz_Chain 1 62.876MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:20:37

802.11ac40_5710MHz_Chain 1 40.440MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:21:26

802.11ac40_5510MHz_Chain 2 49.950MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:57:00

802.11ac40_5550MHz_Chain 2 40.941MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 14:57:56

802.11ac40_5670MHz_Chain 2 57.505MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 15:01:14

802.11ac40_5710MHz_Chain 2 40.841MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 15:02:19

802.11ac80_5530MHz_Chain 0 105.862MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:42:43

802.11ac80_5610MHz_Chain 0 80.480MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:43:35

802.11ac80_5690MHz_Chain 0 80.480MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:44:26

802.11ac80_5530MHz_Chain 1 99.900MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:31:57

802.11ac80_5610MHz_Chain 1 80.280MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:33:02

802.11ac80_5690MHz_Chain 1 80.080MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:36:43

802.11ac80_5530MHz_Chain 2 99.099MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 15:05:17

802.11ac80_5610MHz_Chain 2 80.080MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 15:06:41

802.11ac80_5690MHz_Chain 2 80.080MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 15:07:57

802.11ax160_5570MHz_RU_Full_Chain 0
163.363MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 19:25:56

802.11ax160_5570MHz_RU_Full_Chain 1
163.363MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 13:12:01

802.11ax160_5570MHz_RU_Full_Chain 2
173.774MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 15:31:57

802.11ax20_5500MHz_RU_Full_Chain 0
27.377MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:51:08

802.11ax20_5580MHz_RU_Full_Chain 0
22.725MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:52:50

802.11ax20_5700MHz_RU_Full_Chain 0
22.725MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:54:31

802.11ax20_5720MHz_RU_Full_Chain 0
22.324MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 5.DEC.2024 18:55:52

802.11ax20_5500MHz_RU_Full_Chain 1
26.155MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:45:57

802.11ax20_5580MHz_RU_Full_Chain 1
21.856MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:47:27

802.11ax20_5700MHz_RU_Full_Chain 1
26.534MHz




ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:49:02

802.11ax20_5720MHz_RU_Full_Chain 1
22.366MHz



ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 11:50:24

802.11ax20_5500MHz_RU_Full_Chain 2
25.597MHz



ProjectNo.:2401Y27848E-RF Tester:Allen Bai
Date: 6.DEC.2024 15:14:52