



Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 1 / 6GHz~9GHz




Date: 20. JAN 2018 19:55:39

Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 2 / 6GHz~9GHz




Date: 20. JAN 2018 19:37:26

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 20. JAN 2018 19:56:39

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 20. JAN 2018 19:38:42

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 1 / 6GHz~9GHz




Date: 20. JAN 2018 20:17:01

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 2 / 6GHz~9GHz




Date: 20. JAN 2018 20:43:05

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 20. JAN 2018 20:17:38

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 20. JAN 2018 20:43:54

Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 1 / 6GHz~9GHz




Date: 20.JAN.2018 21:06:45

Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 2 / 6GHz~9GHz




Date: 20.JAN.2018 21:20:34

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 20. JAN 2018 21:07:29

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 20. JAN 2018 21:21:10

Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 1 / 6GHz~9GHz




Date: 20. JAN 2018 21:32:57

Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 2 / 6GHz~9GHz




Date: 20. JAN 2018 21:47:48

Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 20. JAN 2018 21:33:37

Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 20. JAN 2018 21:48:37

Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 1 / 6GHz~9GHz




Date: 20. JAN 2018 22:07:46

Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 2 / 6GHz~9GHz




Date: 20. JAN 2018 22:22:26

Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 20. JAN 2018 22:08:26

Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 20. JAN 2018 22:23:21

Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 1 / 9GHz~18GHz




Date: 20.JAN.2018 19:12:28

Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 2 / 9GHz~18GHz




Date: 20.JAN.2018 19:19:30

Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 20. JAN 2018 19:14:03

Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 20. JAN 2018 19:20:16

Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 1 / 9GHz~18GHz




Date: 20. JAN 2018 19:51:15

Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 2 / 9GHz~18GHz




Date: 20. JAN 2018 19:42:22

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 20. JAN 2018 19:52:30

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 20. JAN 2018 19:43:13

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 1 / 9GHz~18GHz




Date: 20. JAN 2018 20:21:06

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 2 / 9GHz~18GHz




Date: 20. JAN 2018 20:35:04

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 20 JAN 2018 20:22:01

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 20 JAN 2018 20:35:48

Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 1 / 9GHz~18GHz




Date: 20. JAN 2018 21:10:10

Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 2 / 9GHz~18GHz




Date: 20. JAN 2018 21:17:52

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 20. JAN 2018 21:11:07

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 20. JAN 2018 21:18:32

Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 1 / 9GHz~18GHz




Date: 20. JAN 2018 21:36:23

Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 2 / 9GHz~18GHz




Date: 20. JAN 2018 21:44:08

Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 20 JAN 2018 21:37:11

Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 20 JAN 2018 21:44:59

Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 1 / 9GHz~18GHz




Date: 20. JAN 2018 22:11:08

Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 2 / 9GHz~18GHz




Date: 20. JAN 2018 22:18:46


Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 1 / 18GHz~40GHz




Date: 20. JAN 2018 19:15:37

Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 2 / 18GHz~40GHz




Date: 20. JAN 2018 19:18:06

Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 20. JAN 2018 19:16:38

Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 20. JAN 2018 19:18:43

Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 1 / 18GHz~40GHz




Date: 20. JAN 2018 19:48:45

Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 2 / 18GHz~40GHz




Date: 20. JAN 2018 19:45:25

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 20. JAN 2018 19:49:58

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 20. JAN 2018 19:46:53

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 1 / 18GHz~40GHz




Date: 20. JAN 2018 20:23:04

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 2 / 18GHz~40GHz




Date: 20. JAN 2018 20:33:14

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 20. JAN 2018 20:23:48

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 20. JAN 2018 20:33:51

Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 1 / 18GHz~40GHz




Date: 20. JAN 2018 21:13:21

Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 2 / 18GHz~40GHz




Date: 20. JAN 2018 21:16:01

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 20.JAN.2018 21:14:15

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 20.JAN.2018 21:16:44

Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 1 / 18GHz~40GHz




Date: 20.JAN.2018 21:38:36

Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 2 / 18GHz~40GHz




Date: 20.JAN.2018 21:41:35

Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 1 /18GHz~40GHz




Date: 20. JAN 2018 21:39:30

Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 20. JAN 2018 21:42:43

Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 1 / 18GHz~40GHz




Date: 20.JAN.2018 22:13:20

Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 2 / 18GHz~40GHz



Date: 20.JAN.2018 22:16:04




Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 2 / 18GHz~40GHz




For Antenna 2:

Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 1 / 1GHz~3GHz




Date: 7.FEB.2018 21:47:07

Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 2 / 1GHz~3GHz




Date: 7.FEB.2018 21:48:52


Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 7.FEB.2018 22:15:47

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 7.FEB.2018 22:16:39


Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 7.FEB.2018 22:36:07

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 7.FEB.2018 22:35:15


Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 7.FEB.2018 22:38:16

Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 7.FEB.2018 22:39:13


Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 2 / 1GHz~3GHz



Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 2 / 3GHz~6GHz



Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 1 / 3GHz~6GHz




Date: 7.FEB.2018 22:08:41

Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 2 / 3GHz~6GHz



Date: 7.FEB.2018 22:09:43

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 2 / 3GHz~6GHz

