



Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 1 / 3GHz~6GHz




Date: 7.FEB.2018 22:18:52

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 2 / 3GHz~6GHz




Date: 7.FEB.2018 22:17:59


Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 1 / 3GHz~6GHz




Date: 7.FEB.2018 22:30:47

Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 2 / 3GHz~6GHz




Date: 7.FEB.2018 22:32:14

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 7.FEB.2018 22:31:03

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 7.FEB.2018 22:32:42


Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 7.FEB.2018 22:41:46

Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 7.FEB.2018 22:40:43


Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 1 / 3GHz~6GHz




Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 2 / 1 6GHz~9GHz




Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 7.FEB.2018 22:01:11

Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 7.FEB.2018 22:01:59

Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 1 / 6GHz~9GHz




Date: 7.FEB.2018 22:05:56

Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 2 / 6GHz~9GHz




Date: 7.FEB.2018 22:05:05

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 7.FEB.2018 22:05:41

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 7.FEB.2018 22:05:14

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 1 / 6GHz~9GHz




Date: 7.FEB.2018 22:20:47

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 2 / 6GHz~9GHz




Date: 7.FEB.2018 22:21:49

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 7.FEB.2018 22:20:55

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 7.FEB.2018 22:21:26


Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 1 / 6GHz~9GHz




Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 1 / 6GHz~9GHz




Date: 7.FEB.2018 22:47:24

Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 2 / 6GHz~9GHz




Date: 7.FEB.2018 22:46:45


Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 1 / 6GHz~9GHz



Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 2 / 6GHz~9GHz




Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8 FEB. 2018 10:40:32

Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8 FEB. 2018 11:04:35

Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8 FEB. 2018 10:43:21

Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8 FEB. 2018 11:05:08

Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8 FEB. 2018 11:48:38

Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8 FEB. 2018 12:03:01

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8 FEB. 2018 11:50:07

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8 FEB. 2018 12:03:57

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8 FEB. 2018 13:50:48

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8 FEB. 2018 14:01:17

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8 FEB. 2018 13:51:33

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8 FEB. 2018 14:02:22

Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8 FEB. 2018 14:09:32

Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8 FEB. 2018 14:20:01

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8 FEB. 2018 14:10:39

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8 FEB. 2018 14:21:28

Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8 FEB. 2018 14:27:23

Plot on Configuration QPSK, 40M / 5200 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8 FEB. 2018 14:37:49

Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8 FEB. 2018 14:29:53

Plot on Configuration QPSK, 40M / 5200 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8 FEB. 2018 14:38:30

Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8 FEB. 2018 16:47:12

Plot on Configuration QPSK, 40M / 5230 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8 FEB. 2018 16:57:57

Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8 FEB. 2018 16:48:04

Plot on Configuration QPSK, 40M / 5230 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8 FEB. 2018 16:58:41

Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 1 / 18GHz~40GHz




Date: 8 FEB. 2018 10:45:44

Plot on Configuration QPSK, 5M / 5155 MHz / Average / Port 2 / 18GHz~40GHz




Date: 8 FEB. 2018 10:59:31

Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 8 FEB. 2018 10:48:09

Plot on Configuration QPSK, 5M / 5155 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 8 FEB. 2018 11:02:26

Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 1 / 18GHz~40GHz




Date: 8 FEB. 2018 11:52:51

Plot on Configuration QPSK, 5M / 5200 MHz / Average / Port 2 / 18GHz~40GHz




Date: 8 FEB. 2018 12:01:20

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 8 FEB. 2018 11:53:49

Plot on Configuration QPSK, 5M / 5200 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 8 FEB. 2018 12:02:15

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 1 / 18GHz~40GHz




Date: 8 FEB. 2018 13:54:58

Plot on Configuration QPSK, 5M / 5245 MHz / Average / Port 2 / 18GHz~40GHz




Date: 8 FEB. 2018 13:58:10

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 8 FEB. 2018 13:55:47

Plot on Configuration QPSK, 5M / 5245 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 8 FEB. 2018 13:59:43

Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 1 / 18GHz~40GHz




Date: 8 FEB. 2018 14:12:08

Plot on Configuration QPSK, 40M / 5175 MHz / Average / Port 2 / 18GHz~40GHz




Date: 8 FEB. 2018 14:16:55

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 8 FEB. 2018 14:12:52

Plot on Configuration QPSK, 40M / 5175 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 8 FEB. 2018 14:18:25