


### Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:25:38

### Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:26:28


### Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 1 / 9GHz~18GHz



### Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 2 / 9GHz~18GHz




### Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:28:59

### Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:28:02

## Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 9GHz~18GHz



Date: 10.FEB.2018 09:29:15

## Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:28:15


### Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 1 / 9GHz~18GHz



### Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 2 / 9GHz~18GHz




### Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:30:40

### Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 10.FEB.2018 09:31:56

### Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:34:24

### Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:33:01

## Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:34:40

## Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:33:47

### Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:35:35

### Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:36:41

## Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:35:43

## Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:36:58

### Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:39:14

### Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:38:15

## Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 9GHz~18GHz




Date: 10.FEB.2018 09:39:32

## Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 9GHz~18GHz




Date: 10.FEB.2018 09:38:46

### Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:41:35

### Plot on Configuration QPSK, 10M / 5255 MHz / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:42:55

## Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:41:48

## Plot on Configuration QPSK, 10M / 5255 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:43:08

### Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:54:15

### Plot on Configuration QPSK, 10M / 5295 MHz / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:53:19

### Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:54:25

### Plot on Configuration QPSK, 10M / 5295 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:53:28

### Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:55:33

### Plot on Configuration QPSK, 10M / 5340 MHz / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:56:52

### Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:55:45

### Plot on Configuration QPSK, 10M / 5340 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:57:04

### Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:59:44

### Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:58:38

### Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 09:59:57

### Plot on Configuration QPSK, 10M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 09:58:57

### Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:02:19

### Plot on Configuration QPSK, 40M / 5270 MHz / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:04:02

### Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:02:49

### Plot on Configuration QPSK, 40M / 5270 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:04:16


### Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 1 / 18GHz~40GHz



### Plot on Configuration QPSK, 40M / 5300 MHz / Average / Port 2 / 18GHz~40GHz




## Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:06:58

## Plot on Configuration QPSK, 40M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:05:34

### Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:07:53

### Plot on Configuration QPSK, 40M / 5325 MHz / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:08:45

### Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:08:02

### Plot on Configuration QPSK, 40M / 5325 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:08:57

### Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 1 / 18GHz~40GHz




Date: 10.FEB.2018 10:10:41

### Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Average / Port 2 / 18GHz~40GHz




Date: 10.FEB.2018 10:09:56


## Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 1 / 18GHz~40GHz



## Plot on Configuration QPSK, 40M / 5250 MHz (Straddle Channel) / Peak / Port 2 / 18GHz~40GHz




### Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 11:27:13

### Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 11:23:03

### Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 10.FEB.2018 11:28:56

### Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 2 / 1GHz~3GHz



Date: 10.FEB.2018 11:26:37


### Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 1 / 1GHz~3GHz



### Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 2 / 1GHz~3GHz




### Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 11:40:59

### Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 11:44:09

### Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 11:50:05

### Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 11:47:36

## Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 11:50:19

## Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 11:48:14

### Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 11:54:13

### Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 11:58:30

## Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 11:54:27

## Plot on Configuration QPSK, 10M / 5725 MHz (Straddle Channel) / Peak / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 11:58:40

### Plot on Configuration QPSK, 40M / 5495 MHz / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 12:07:57

### Plot on Configuration QPSK, 40M / 5495 MHz / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 12:04:39

## Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 12:08:11

## Plot on Configuration QPSK, 40M / 5495 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 12:05:05

### Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 12:12:11

### Plot on Configuration QPSK, 40M / 5550 MHz / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 12:14:44

## Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 1 / 1GHz~3GHz



Date: 10.FEB.2018 12:12:26

## Plot on Configuration QPSK, 40M / 5550 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 12:15:08


### Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 1 / 1GHz~3GHz




### Plot on Configuration QPSK, 40M / 5700 MHz / Average / Port 2 / 1GHz~3GHz




### Plot on Configuration QPSK, 40M / 5700 MHz / Peak / Port 1 / 1GHz~3GHz



### Plot on Configuration QPSK, 40M / 5700 MHz / Peak / Port 2 / 1GHz~3GHz




### Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 1 / 1GHz~3GHz




Date: 10.FEB.2018 12:35:50

### Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Average / Port 2 / 1GHz~3GHz




Date: 10.FEB.2018 12:40:14

### Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 1 / 1GHz~3GHz



Date: 10.FEB.2018 12:36:00

### Plot on Configuration QPSK, 40M / 5720 MHz (Straddle Channel) / Peak / Port 2 / 1GHz~3GHz



Date: 10.FEB.2018 12:40:26

### Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 1 / 3GHz~6GHz




Date: 10.FEB.2018 11:27:29

### Plot on Configuration QPSK, 10M / 5480 MHz / Average / Port 2 / 3GHz~6GHz




Date: 10.FEB.2018 11:23:38

### Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 1 / 3GHz~6GHz



### Plot on Configuration QPSK, 10M / 5480 MHz / Peak / Port 2 / 3GHz~6GHz



### Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 1 / 3GHz~6GHz




Date: 10.FEB.2018 11:41:35

### Plot on Configuration QPSK, 10M / 5575 MHz / Average / Port 2 / 3GHz~6GHz




Date: 10.FEB.2018 11:43:12


### Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 1 / 3GHz~6GHz




### Plot on Configuration QPSK, 10M / 5575 MHz / Peak / Port 2 / 3GHz~6GHz




### Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 1 / 3GHz~6GHz



### Plot on Configuration QPSK, 10M / 5715 MHz / Average / Port 2 / 3GHz~6GHz



## Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 1 / 3GHz~6GHz



## Plot on Configuration QPSK, 10M / 5715 MHz / Peak / Port 2 / 3GHz~6GHz

