





Appendix II

Setup Photographs


RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)
MEASUREMENT POSITION---condition 1




MEASUREMENT POSITION (X axis) ---condition 1




MEASUREMENT POSITION (Y axis) ---condition 1




MEASUREMENT POSITION (Z axis) ---condition 1




MEASUREMENT POSITION---condition 2




MEASUREMENT POSITION (X axis) ---condition 2




MEASUREMENT POSITION (Y axis) ---condition 2




MEASUREMENT POSITION (Z axis) ---condition 2




MEASUREMENT POSITION---condition 3




MEASUREMENT POSITION (X axis) ---condition 3




MEASUREMENT POSITION (Y axis) ---condition 3




MEASUREMENT POSITION (Z axis) ---condition 3




MEASUREMENT POSITION---condition 4




MEASUREMENT POSITION (X axis) ---condition 4




MEASUREMENT POSITION (Y axis) ---condition 4



MEASUREMENT POSITION (Z axis) ---condition 4




MEASUREMENT POSITION---condition 5




MEASUREMENT POSITION (X axis) ---condition 5




MEASUREMENT POSITION (Y axis) ---condition 5



MEASUREMENT POSITION (Z axis) ---condition 5



RADIATED RF MEASUREMENT SETUP (30MHz~1GHz) ---condition 3



RADIATED RF MEASUREMENT SETUP (Below 30MHz) ---condition 3



POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP---condition 3

