



15MHz_Low_16QAM_1@0 -25.17dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:15:18

15MHz_Low_16QAM_75@0 -26.83dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:15:09

15MHz_High_QPSK_1@74 -24.26dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:27:39

15MHz_High_QPSK_75@0 -29.40dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:27:29

15MHz_High_16QAM_1@74 -24.52dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:15:55

15MHz_High_16QAM_75@0 -29.93dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:15:45

20MHz_Low_QPSK_1@0 -30.77dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 16:28:44

20MHz_Low_QPSK_100@0 -26.81dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 16:28:34

20MHz_Low_16QAM_1@0 -30.42dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:17:20

20MHz_Low_16QAM_100@0 -28.13dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:17:10

20MHz_High_QPSK_1@99 -31.17dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 16:29:21

20MHz_High_QPSK_100@0 -31.93dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 16:29:11

20MHz_High_16QAM_1@99 -31.93dBm



ProjectNo: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:17:56


20MHz_High_16QAM_100@0 -31.32dBm



ProjectNo: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:17:46


B38 , Normal

5MHz_Low_QPSK_1@0 -20.99dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 16:43:53

5MHz_Low_QPSK_25@0 -22.81dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 16:43:43

5MHz_Low_16QAM_1@0 -22.29dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:23:54

5MHz_Low_16QAM_25@0 -25.43dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:23:45

5MHz_High_QPSK_1@24 -16.96dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:44:32

5MHz_High_QPSK_25@0 -20.49dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:44:21

5MHz_High_16QAM_1@24 -20.59dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:24:28

5MHz_High_16QAM_25@0 -25.43dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:24:18

10MHz_Low_QPSK_1@0 -23.93dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:45:40

10MHz_Low_QPSK_50@0 -25.52dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:45:30

10MHz_Low_16QAM_1@0 -25.20dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:25:29

10MHz_Low_16QAM_50@0 -28.89dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:25:19

10MHz_High_QPSK_1@49 -24.42dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:46:19

10MHz_High_QPSK_50@0 -26.62dBm




ProjectNo: RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:46:09

10MHz_High_16QAM_1@49 -24.24dBm



ProjectNo: RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:26:06

10MHz_High_16QAM_50@0 -27.11dBm



ProjectNo: RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:25:56