



15MHz_Low_QPSK_75@0 -26.25dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21.JUN.2024 16:47:20

15MHz_Low_16QAM_75@0 -29.13dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:26:59

15MHz_High_QPSK_75@0 -23.52dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21.JUN.2024 16:47:59

15MHz_High_16QAM_1@74 -17.84dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:27:44

15MHz_High_16QAM_75@0 -26.32dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:27:34

20MHz_Low_QPSK_1@0 -20.87dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:49:21

20MHz_Low_QPSK_100@0 -28.61dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 21 JUN 2024 16:49:11

20MHz_Low_16QAM_1@0 -19.50dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:28:45

20MHz_Low_16QAM_100@0 -29.31dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
 Date: 2 JUL 2024 10:28:36

20MHz_High_QPSK_1@99 -19.67dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 16:50:01

20MHz_High_QPSK_100@0 -25.63dBm




ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 21 JUN 2024 16:49:50

20MHz_High_16QAM_1@99 -22.75dBm



ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:29:21

20MHz_High_16QAM_100@0 -29.44dBm



ProjectNo.:RKSA240112001 Tester:Jason Lu
Date: 2 JUL 2024 10:29:11