

Internal photos FLIR-K1870 camera.



Figur 1 FLIR-K1340 Display side.



Figur 2 FLIR K1340 Left side.

This document does not contain export-controlled information.  
Teledyne Confidential; Commercially Sensitive Business Data  
This document does not contain export-controlled information.  
Teledyne Confidential; Commercially Sensitive Business Data



Figur 3 FLIR-K1340 Right side.



Figur 4 FLIR-K1340 Front side.




Figure 5 Top view, USB C connector visible.






Figure 6 Front cone removed.




Figur 7 Display side, cover removed.




Figur 8 Window, back side.




Figur 9 Display side, Window removed.




Figur 10 Display side, Core removed.




Figur 11 Core, front side.



Figur 12 Core, computer board removed.



Figur 13 EC 701, computer board, primary side.



Figur 14 EC 701, secondary side.




Figure 15 LUBI battery interface board.



Figure 1 DAT64F Primary side




Figure 2 DAT64F Secondary side




Figure 3 Detector




Figure 4 EC701 with detector module, cover off.

