




Fig.43




Fig.44




Fig.45




Fig.46




Fig.47




Fig.48




Fig.49




Fig.50




Fig.51




Fig.52




Fig.53




Fig.54

4 Peak-Average Ratio

Band	Carrier frequency (MHz)	Channel	BW (MHz)	RB Size	RB Offset	QPSK	16-QAM	64-QAM
25	1850.7	26047	1.4	1	5	Fig.1	Fig.2	Fig.3
25	1850.7	26047	1.4	6	0	Fig.4	Fig.5	Fig.6
25	1882.5	26365	1.4	1	5	Fig.7	Fig.8	Fig.9
25	1882.5	26365	1.4	6	0	Fig.10	Fig.11	---
25	1914.3	26683	1.4	1	5	Fig.12	Fig.13	Fig.14
25	1914.3	26683	1.4	6	0	Fig.15	Fig.16	Fig.17
25	1851.5	26055	3	1	14	Fig.18	Fig.19	Fig.20
25	1851.5	26055	3	15	0	Fig.21	Fig.22	Fig.23
25	1882.5	26365	3	1	14	Fig.24	Fig.25	Fig.26
25	1882.5	26365	3	15	0	Fig.27	Fig.28	Fig.29
25	1913.5	26675	3	1	14	Fig.30	Fig.31	Fig.32
25	1913.5	26675	3	15	0	Fig.33	Fig.34	Fig.35
25	1852.5	26065	5	1	24	Fig.36	Fig.37	Fig.38
25	1852.5	26065	5	25	0	Fig.39	Fig.40	Fig.41
25	1882.5	26365	5	1	24	Fig.42	Fig.43	Fig.44
25	1882.5	26365	5	25	0	Fig.45	Fig.46	Fig.47
25	1912.5	26665	5	1	24	Fig.48	Fig.49	Fig.50
25	1912.5	26665	5	25	0	Fig.51	Fig.52	Fig.53
25	1855	26090	10	1	49	Fig.54	Fig.55	Fig.56
25	1855	26090	10	50	0	Fig.57	Fig.58	Fig.59
25	1882.5	26365	10	1	49	Fig.60	Fig.61	Fig.62
25	1882.5	26365	10	50	0	Fig.63	Fig.64	Fig.65
25	1910	26640	10	1	49	Fig.66	Fig.67	Fig.68
25	1910	26640	10	50	0	Fig.69	Fig.70	Fig.71
25	1857.5	26115	15	1	74	Fig.72	Fig.73	Fig.74
25	1857.5	26115	15	75	0	Fig.75	Fig.76	Fig.77
25	1882.5	26365	15	1	74	Fig.78	Fig.79	Fig.80
25	1882.5	26365	15	75	0	Fig.81	Fig.82	Fig.83
25	1907.5	26615	15	1	74	Fig.84	Fig.85	Fig.86
25	1907.5	26615	15	75	0	Fig.87	Fig.88	Fig.89
25	1860	26140	20	1	99	Fig.90	Fig.91	Fig.92
25	1860	26140	20	100	0	Fig.93	Fig.94	Fig.95
25	1882.5	26365	20	1	99	Fig.96	Fig.97	Fig.98
25	1882.5	26365	20	100	0	Fig.99	Fig.100	Fig.101
25	1905	26590	20	1	99	Fig.102	Fig.103	Fig.104
25	1905	26590	20	100	0	Fig.105	Fig.106	Fig.107




Fig.1




Fig.2




Fig.3




Fig.4




Fig.5




Fig.6




Fig.7




Fig.8




Fig.9




Fig.10




Fig.11




Fig.12




Fig.13




Fig.14




Fig.15




Fig.16




Fig.17




Fig.18




Fig.19




Fig.20




Fig.21




Fig.22




Fig.23




Fig.24




Fig.25




Fig.26




Fig.27




Fig.28




Fig.29




Fig.30




Fig.31




Fig.32




Fig.33




Fig.34




Fig.35




Fig.36




Fig.37




Fig.38




Fig.39




Fig.40




Fig.41




Fig.42




Fig.43




Fig.44




Fig.45




Fig.46




Fig.47




Fig.48




Fig.49




Fig.50




Fig.51




Fig.52




Fig.53




Fig.54