



1_3MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 22:59:56

1_3MHz_High_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:00:06

1_3MHz_High_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:00:33

1_3MHz_High_QPSK_15@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:00:42

1_5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:01:10

1_5MHz_Low_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:01:19

1_5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Uain Ou
Date: 13.FEB.2025 23:01:45

1_5MHz_Low_QPSK_25@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Uain Ou
Date: 13.FEB.2025 23:01:54

1_5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Uain Ou
Date: 13.FEB.2025 23:02:20

1_5MHz_High_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Uain Ou
Date: 13.FEB.2025 23:02:29

1_5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Uain Ou
Date: 13.FEB.2025 23:02:55

1_5MHz_High_QPSK_25@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Uain Ou
Date: 13.FEB.2025 23:03:04

1_10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:03:32

1_10MHz_Low_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:03:41

1_10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:04:08

1_10MHz_Low_QPSK_50@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:04:17

1_15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:04:48

1_15MHz_Low_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:04:57

1_15MHz_Low_QPSK_75@0(30MHz~1GHz)



ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:05:23

1_15MHz_Low_QPSK_75@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:05:32

B26_3 , Normal


1RB was the worst case

3_1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:25:14

3_1.4MHz_Middle_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:25:25

3_1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:25:55

3_1.4MHz_Middle_QPSK_6@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:26:05

3_3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:26:37

3_3MHz_Middle_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:26:47

3_3MHz_Middle_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:27:16

3_3MHz_Middle_QPSK_15@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:27:25

3_5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:28:05

3_5MHz_Middle_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:28:15

3_5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:28:45

3_5MHz_Middle_QPSK_25@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:28:54

3_10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:29:25

3_10MHz_Middle_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:29:35

3_10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:30:04

3_10MHz_Middle_QPSK_50@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:30:14

3_15MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:30:45

3_15MHz_Middle_QPSK_1@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:30:55

3_15MHz_Middle_QPSK_75@0(30MHz~1GHz)



ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:31:25

3_15MHz_Middle_QPSK_75@0(1GHz~9.24GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:31:35

FCC Part 22H

B5 , Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:47:54

1.4MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:48:02

1.4MHz_Low_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:48:25

1.4MHz_Low_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:48:33

1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:48:55

1.4MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:49:03

1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:49:25

1.4MHz_Middle_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:49:33

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:49:55

1.4MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:50:03

1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:50:25

1.4MHz_High_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:50:33

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:50:59

3MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:51:07

3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:51:30

3MHz_Low_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:51:38

3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:52:00

3MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:52:08

3MHz_Middle_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:52:31

3MHz_Middle_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:52:38

3MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:53:01

3MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:53:09

3MHz_High_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:53:31

3MHz_High_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:53:39

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:54:04

5MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:54:11

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:54:34

5MHz_Low_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:54:42

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:55:05

5MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:55:13

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:55:36

5MHz_Middle_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:55:44

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:56:06

5MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:56:14

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:56:37

5MHz_High_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:56:45

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:57:11

10MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:57:19

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:57:42

10MHz_Low_QPSK_50@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:57:50

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:58:13

10MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:58:21

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:58:45

10MHz_Middle_QPSK_50@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:58:53

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:59:16

10MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:59:25

10MHz_High_QPSK_50@0(30MHz~1GHz)



ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:59:48

10MHz_High_QPSK_50@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 21:59:56

B26_2 , Normal


1RB was the worst case

2_1.4MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:06:13

2_1.4MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:06:22

2_1.4MHz_Low_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:06:48

2_1.4MHz_Low_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:06:57

2_1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:07:24

2_1.4MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:07:33

2_1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:08:00

2_1.4MHz_Middle_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:08:09

2_1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:08:35

2_1.4MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:08:44

2_1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:09:11

2_1.4MHz_High_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:09:21

2_3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:09:51

2_3MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:10:01

2_3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:10:29

2_3MHz_Low_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:10:38

2_3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:11:04

2_3MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:11:14

2_3MHz_Middle_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:11:41

2_3MHz_Middle_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:11:50

2_3MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:12:17

2_3MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:12:26

2_3MHz_High_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:12:54

2_3MHz_High_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:13:03

2_5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:13:32

2_5MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:13:42

2_5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:14:09

2_5MHz_Low_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:14:19

2_5MHz_Middle_QPSK_1@0(30MHz~1GHz)



ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:14:46

2_5MHz_Middle_QPSK_1@0(1GHz~9.49GHz)



ProjectNo.:2501P42033E-RF Tester:Usain Ou
Date: 13.FEB.2025 23:14:55