



PHOTOGRAPHS OF TEST SETUP


Test Model No.: S988



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Radiated spurious emission Test Setup-3Above 1GHz
There are absorbing materials under the ground.

Report No. : EED32N80998107

Page 43 of 43

PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No. EED32N80998101 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp. The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

*** End of Report ***

