




Appendix III


Setup Photographs



Conducted Disturbance



Radiated Disturbance below 1 GHz and Above 30 MHz





Radiated Disturbance Below 30 MHz



Radiated Disturbance above 1GHz



For all radiated test, EUT in X and Y axis emissions had been tested, but only the worst case (Y axis) data recorded in the report.