



PHOTOGRAPHS OF TEST SET UP



Figure 1 – Radiated Disturbance - 30 MHz to 1 GHz




Figure 2 – Radiated Disturbance - 1 GHz to 8 GHz




Figure 3 – Radiated Disturbance - 8 GHz to 18 GHz




Figure 4 – Radiated Disturbance - 18 GHz to 26 GHz




Figure 5 – DUT bottom edge at 0mm gap configuration




Figure 6 – DUT Back face at 0mm gap configuration




Figure 7 – DUT right edge at 0mm gap configuration




Figure 8 – DUT left edge at 0mm gap configuration

FCC ID: 2A4DE3S001
IC: 28188-3S001

3Shape TRIOS A/S
Handheld Dental Scanner, Model: L1P-2




Figure 9 – DUT front face at 0mm gap configuration