



Internal Photos of the EUT




Fig. 1




Fig. 2






Fig. 3





Fig. 4





Compliance Testing Laboratory
Bldg A & 301 Bldg C, Juji Industrial Zone






Fig. 7




Fig. 8






Fig. 9




Fig. 10





Fig. 11

