


APPENDIX 3: Photographs of test setup

Radiated Spurious Emission

EUT: Left
Front




EUT: Right
Front




Rear (Below 1 GHz)




Rear (Below 1 GHz)



Rear (Above 1 GHz)



Rear (Above 1 GHz)



Pre-check of Worst Case Position

EUT: Left
X-axis



Y-axis



Z-axis



EUT: Right
X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1



Photo 2

End of Report