



PHOTOGRAPHS OF TEST SETUP




Test Setup of Top (Mode a)




Test Setup of Top (Mode b to Mode e)




Test Setup of Front (Mode a)




Test Setup of Front (Mode b to Mode e)




Test Setup of Left (Mode a)



Test Setup of Left (Mode b to Mode e)




Test Setup of Rear (Mode a)



Test Setup of Rear (Mode b to Mode e)



Test Setup of Right (Mode a)



Test Setup of Right (Mode b to Mode e)

PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No. EED32Q80173001 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

*** End of Report ***