

Prüfbericht-Nr.:
Test Report No.:

JP22LCNL 001

Seite 29 von 34
Page 29 of 34

7. Photographs of the Test Setup

Photograph 4: Set-up for Frequency Stability, General View



Photograph 5: Set-up for Frequency Stability, inside Temperature Chamber



Prüfbericht-Nr.:
Test Report No.:


JP22LCNL 001

Seite 30 von 34
Page 30 of 34

**Photograph 6: Set-up for AC Power Line Conducted Emission of Transmitter,
Front View**



**Photograph 7: Set-up for AC Power Line Conducted Emission of Transmitter,
Rear View**




Prüfbericht-Nr.:
Test Report No.:

JP22LCNL 001

Seite 31 von 34
Page 31 of 34

Photograph 8: Set-up for Radiated Emission of Transmitter Below 30MHz, Front View



Photograph 9: Set-up for Radiated Emission of Transmitter Below 30MHz, Rear View



Prüfbericht-Nr.:
Test Report No.:

JP22LCNL 001

Seite 32 von 34
Page 32 of 34

Photograph 10: Set-up for Radiated Emission of Transmitter, Front View



Photograph 11: Set-up for Radiated Emission of Transmitter, Rear View

