













8.2.7 Conducted RF Spurious Emission



Condition	Mode	Frequency (MHz)	Antenna	Max Value (dBc)	Limit (dBc)	Verdict
NVNT	ax20	2412	Ant1	-50.28	-20	Pass
NVNT	ax20	2412	Ant2	-47.52	-20	Pass
NVNT	ax20	2437	Ant1	-53.35	-20	Pass
NVNT	ax20	2437	Ant2	-48.6	-20	Pass
NVNT	ax20	2462	Ant1	-51.75	-20	Pass
NVNT	ax20	2462	Ant2	-47.83	-20	Pass
NVNT	ax40	2422	Ant1	-40.25	-20	Pass
NVNT	ax40	2422	Ant2	-44.3	-20	Pass
NVNT	ax40	2437	Ant1	-47.76	-20	Pass
NVNT	ax40	2437	Ant2	-47.98	-20	Pass
NVNT	ax40	2452	Ant1	-48.67	-20	Pass
NVNT	ax40	2452	Ant2	-45.55	-20	Pass
NVNT	n20	2412	Ant1	-50.53	-20	Pass
NVNT	n20	2412	Ant2	-48.73	-20	Pass
NVNT	n20	2437	Ant1	-51.77	-20	Pass
NVNT	n20	2437	Ant2	-44.79	-20	Pass
NVNT	n20	2462	Ant1	-52.7	-20	Pass
NVNT	n20	2462	Ant2	-49.26	-20	Pass
NVNT	n40	2422	Ant1	-47.93	-20	Pass
NVNT	n40	2422	Ant2	-43.14	-20	Pass
NVNT	n40	2437	Ant1	-47.88	-20	Pass
NVNT	n40	2437	Ant2	-48.44	-20	Pass
NVNT	n40	2452	Ant1	-47.32	-20	Pass
NVNT	n40	2452	Ant2	-46.62	-20	Pass























































































END OF REPORT