


Page 36 of 60 Report No.: EED32O81454801

5 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz) (small)



Radiated spurious emission Test Setup-2(Below 1GHz) (small) Close up















Report No.: EED32O81454801





Radiated spurious emission Test Setup-3(Below 1GHz) (big)



Radiated spurious emission Test Setup-4(Below 1GHz) (big) Close up
















Report No.: EED32O81454801





Radiated spurious emission Test Setup-5(Above 1GHz)(small)



Radiated spurious emission Test Setup-6(Above 1GHz)(big)













Report No.: EED32O81454801







Radiated spurious emission Test Setup-7(Above 1GHz)
There are absorbing materials under the ground.





















































