

**Annex A EUT Photographs, external**

Photo No. 1: radiated test sample




Photo No. 2: radiated test sample





Photo No. 3: radiated test sample



Photo No. 4: conducted test sample






Photo No. 5: conducted test sample





Photo No. 6: conducted test sample



Photo No. 7: DC power supply cable / adapter to OBD connector





## Annex B EUT Photographs, internal

Photo No. 8: radiated test sample




Photo No. 9: radiated test sample






Photo No. 10: radiated test sample



Photo No. 11: radiated test sample





Photo No. 12: radiated test sample




Photo No. 13: radiated test sample





Photo No. 14: radiated test sample




Photo No. 15: radiated test sample






Photo No. 16: radiated test sample




Photo No. 17: radiated test sample






Photo No. 18: radiated test sample




Photo No. 19: radiated test sample






Photo No. 20: radiated test sample





Photo No. 21: radiated test sample





TR No.: 24080432-41494-0

2025-02-17

Photo No. 22: conducted test sample




Photo No. 23: conducted test sample conducted test sample conducted test samplev






Photo No. 24: conducted test sample

